

# ISO 22574:2023-08 (E)

## Road vehicles - Brake linings friction materials - Visual inspection

---

| <b>Contents</b>    |  | <b>Page</b> |
|--------------------|--|-------------|
| Foreword .....     |  | v           |
| Introduction ..... |  | vi          |
| <b>1</b>           | <b>Scope .....</b>   | <b>1</b>    |
| <b>2</b>           | <b>Normative references .....</b>                                  | <b>1</b>    |
| <b>3</b>           | <b>Terms and definitions .....</b>                                 | <b>1</b>    |
| <b>4</b>           | <b>Characteristic features for friction materials .....</b>        | <b>1</b>    |
| 4.1                | Characteristic features for disc brake pads .....                  | 1           |
| 4.1.1              | Gapping between material and plate .....                           | 1           |
| 4.1.2              | Edge chipping .....  | 2           |
| 4.1.3              | Splits .....   | 2           |
| 4.1.4              | Minor splits .....   | 3           |
| 4.1.5              | Plucked and indented spigots .....                                 | 3           |
| 4.1.6              | Poor consolidated spigot holes .....                               | 3           |
| 4.1.7              | Excess adhesive on plate .....                                     | 4           |
| 4.1.8              | Material flash on plate .....                                      | 4           |
| 4.1.9              | Abrasive coating .....   | 5           |
| 4.1.10             | Anti-noise coating runs .....                                      | 5           |
| 4.1.11             | Skin crazing .....   | 6           |
| 4.1.12             | Underlayer distribution .....                                      | 6           |
| 4.1.13             | Marking .....  | 7           |
| 4.1.14             | Unground material surface .....                                    | 7           |
| 4.1.15             | Paint on friction material surface .....                           | 7           |
| 4.1.16             | Surface blisters .....   | 8           |
| 4.1.17             | Surface indentations .....   | 8           |
| 4.1.18             | Grinding marks on friction surface .....                           | 9           |
| 4.1.19             | High porosity area .....   | 9           |
| 4.1.20             | Poorly consolidated friction material .....                        | 10          |
| 4.1.21             | Surface contamination with foreign matters .....                   | 10          |
| 4.1.22             | Surface contamination with similar friction materials .....        | 11          |
| 4.1.23             | Friction surface structure .....                                   | 11          |
| 4.1.24             | Plate scratched and dents .....                                    | 12          |
| 4.1.25             | Blanking burrs .....   | 12          |
| 4.1.26             | Deformation by blanking and edge chipping at functional area ..... | 13          |
| 4.1.27             | Edge shipping at pin area .....                                    | 13          |
| 4.1.28             | Pinholes (Side-cut cavity) .....                                   | 14          |
| 4.1.29             | Grinding marks on the carrier .....                                | 14          |
| 4.1.30             | Spring holder defects .....  | 15          |
| 4.1.31             | Surface deepening .....  | 15          |
| 4.1.32             | Cold laps .....  | 16          |
| 4.2                | Characteristic features for drum brake linings .....               | 16          |
| 4.2.1              | Chipped edges/corners .....  | 16          |
| 4.2.2              | Edge splits .....  | 17          |
| 4.2.3              | Drill hole chipping at lining ends .....                           | 18          |
| 4.2.4              | Drill hole burrs inside the surface .....                          | 18          |
| 4.2.5              | Drill hole burrs outside the surface .....                         | 18          |
| 4.2.6              | Cracks radiating from the rivet hole .....                         | 19          |
| 4.2.7              | Paint on surface - Lining for riveting and bonding .....           | 19          |

|        |   |    |
|--------|---|----|
| 4.2.8  | Surface cracks .....  | 20 |
| 4.2.9  | Marking .....   | 20 |
| 4.2.10 | Moulding skin on inside radius surface - linings for bonding and riveting .....     | 21 |
| 4.2.11 | Moulding skin on outside radius surface - linings for riveting or bonding .....     | 21 |
| 4.2.12 | Surface blisters .....  | 22 |
| 4.2.13 | Surface grind marks .....   | 22 |
| 4.2.14 | Pitted surface (plucked surface) .....  | 23 |
| 4.2.15 | Surface structure .....   | 23 |
| 4.2.16 | Poor consolidated friction material .....   | 24 |
| 4.2.17 | Inside surface indentations .....   | 24 |
| 4.2.18 | Outside surface indentations .....  | 25 |
| 4.2.19 | Concentration of self-contained ingredients unless typical of the formulation ..... | 26 |
| 4.2.20 | High porosity area .....  | 27 |
| 4.2.21 | Metal wire or plastic reinforcement .....   | 27 |
| 4.2.22 | Foreign matter friction surface inclusion .....                                     | 28 |
| 4.3    | Characteristic features for bonded lined shoes .....                                | 28 |
| 4.3.1  | Lining overhang on shoe platform edge .....   | 28 |
| 4.3.2  | Faulty shoes .....  | 29 |
| 4.3.3  | Restricted lever movement .....   | 29 |
| 4.3.4  | Stencilled information .....  | 30 |
| 4.3.5  | Excess adhesive exudation over shoe platform edges .....                            | 31 |
| 4.3.6  | Excess adhesive exudation from lining ends .....                                    | 31 |
| 4.3.7  | Excess primer .....   | 32 |
| 4.3.8  | Lining surface condition .....  | 32 |
| 4.3.9  | Gaps between linings and shoe platform .....  | 34 |