DIN EN ISO 18217:2015-12 (E)

Safety of woodworking machines - Edge-banding machines fed by chain(s) (ISO 18217:2015)

4 List of significant hazards13	Co	ontent	S		Page			
Scope	Eur	opean f	oreword		4			
1 Scope 7 2 Normative references 8 3 Terms and definitions 8 4 List of significant hazards 13 5 Safety requirements and/or protective measures 15 5.1 General 15 5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4	Fore	oreword						
1 Scope 7 2 Normative references 8 3 Terms and definitions 8 4 List of significant hazards 13 5 Safety requirements and/or protective measures 15 5.1 General 15 5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4	Intr	oductio	n		6			
2 Normative references 8 3 Terms and definitions 8 4 List of significant hazards 13 5 Safety requirements and/or protective measures 15 5.1 General 15 5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of the control circuits 21 5.2.9 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.3 Trotection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.4 Braking 24 <								
Safety requirements and/or protective measures 15		_						
4 List of significant hazards 13 5 Safety requirements and/or protective measures 15 5.1 General. 15 5.2 Controls. 16 5.2.1 Safety and reliability of control systems. 16 5.2.2 Position of controls. 16 5.2.3 Starting. 17 5.2.4 Stop controls. 17 5.2.5 Integrated feed. 18 5.2.6 Mode selection. 19 5.2.7 Overspeed control for milling tools. 20 5.2.8 Failure of any power supply. 20 5.2.9 Failure of the control circuits. 21 5.2.10 Tele-service. 21 5.3.1 Stability. 21 5.3.2 Risk of break-up during operation. 22 5.3.3 Tool holder and tool design. 22 5.3.4 Braking. 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back. 24 5.3.6 Work-piece supports and guides. 25 5.4.7 Protection against non-	2	Norn	native re	eferences	8			
5 Safety requirements and/or protective measures 15 5.1 General 15 5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and g	3	Tern	ns and do	efinitions	8			
5 Safety requirements and/or protective measures 15 5.1 General 15 5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and g	4	List	of signifi	cant hazards	13			
5.1 General .15 5.2 Controls .16 5.2.1 Safety and reliability of control systems .16 5.2.2 Position of controls .16 5.2.3 Starting .17 5.2.4 Stop controls .17 5.2.5 Integrated feed .18 5.2.6 Mode selection .19 5.2.7 Overspeed control for milling tools .20 5.2.8 Failure of any power supply .20 5.2.9 Failure of the control circuits .21 5.2.10 Tele-service .21 5.3 Protection against mechanical hazards .21 5.3.1 Stability .21 5.3.2 Risk of break-up during operation .22 5.3.3 Tool holder and tool design .22 5.3.4 Braking .24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back .24 5.3.6 Work-piece supports and guides .25 5.3.7 Prevention of access to moving parts .27 5.4 Protection agains	5							
5.2 Controls 16 5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Stability 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34		5.1 General						
5.2.1 Safety and reliability of control systems 16 5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust		_						
5.2.2 Position of controls 16 5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust <		J						
5.2.3 Starting 17 5.2.4 Stop controls 17 5.2.5 Integrated feed 18 5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37								
5.2.4 Stop controls. 17 5.2.5 Integrated feed 18 5.2.6 Mode selection. 19 5.2.7 Overspeed control for milling tools. 20 5.2.8 Failure of any power supply. 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service. 21 5.3 Protection against mechanical hazards. 21 5.3.1 Stability. 21 5.3.2 Risk of break-up during operation. 22 5.3.3 Tool holder and tool design. 22 5.3.4 Braking. 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back. 24 5.3.6 Work-piece supports and guides. 25 5.3.7 Prevention of access to moving parts. 27 5.4 Protection against non-mechanical hazards. 34 5.4.1 Fire. 34 5.4.2 Noise. 35 5.4.3 Emission of chips and dust. 36 5.4.4 Electricity. 37 5.4.5 Ergonomics a			5.2.3					
52.5 Integrated feed								
5.2.6 Mode selection 19 5.2.7 Overspeed control for milling tools 20 5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics </td <td rowspan="6"></td> <td></td> <td>5.2.5</td> <td></td> <td></td>			5.2.5					
5.2.8 Failure of any power supply 20 5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.10 Isolation			5.2.6					
5.2.9 Failure of the control circuits 21 5.2.10 Tele-service 21 5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.10 Isolation 38 5.4.11 Maintenance 39			5.2.7	Overspeed control for milling tools	20			
5.2.10 Tele-service			5.2.8	Failure of any power supply	20			
5.3 Protection against mechanical hazards 21 5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.14 Substances 39 <td></td> <td>5.2.9</td> <td></td> <td></td>			5.2.9					
5.3.1 Stability 21 5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.14 Substances 39								
5.3.2 Risk of break-up during operation 22 5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.14 Substances 39		5.3						
5.3.3 Tool holder and tool design 22 5.3.4 Braking 24 5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back 24 5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39				Stability	21			
5.3.4 Braking								
5.3.5 Devices to minimize the possibility or the effect of ejection or kick-back								
5.3.6 Work-piece supports and guides 25 5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.3.7 Prevention of access to moving parts 27 5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4 Protection against non-mechanical hazards 34 5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.1 Fire 34 5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39		_						
5.4.2 Noise 35 5.4.3 Emission of chips and dust 36 5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39		5.4		8				
5.4.3 Emission of chips and dust								
5.4.4 Electricity 37 5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39				Noise	35			
5.4.5 Ergonomics and handling 37 5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39			0.1.0	Emission of chips and dust	36			
5.4.6 Lighting 38 5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.7 Pneumatics and hydraulics 38 5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.8 Electromagnetic compatibility 38 5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.9 Static electricity 38 5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.10 Isolation 38 5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.11 Maintenance 39 5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.12 Errors of fitting 39 5.4.13 Heat 39 5.4.14 Substances 39								
5.4.13 Heat								
5.4.14 Substances								

6	Infor	mation for use	39	
	6.1	Warning devices	39	
	6.2	Warning devicesMarking	40	
	6.3	Instruction handbook	41	
Annex	A (no	rmative) Braking tests	45	
Annex	B (no	rmative) Impact test method for guards	47	
Annex C (normative) Stability test for displaceable machines				
Annex D (informative) Performance level required				
Annex	ZA (i	nformative) Relationship between this European Standard and the Essential		
	Requ	irements of EU Directive 2006/42/EC	53	
Biblio	graph	y	54	