

ISO 23063:2024-11 (E)

Foundry machinery - Safety requirements for high pressure die casting machines

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	3
4	List of significant hazards	7
4.1	General	7
4.2	Mechanical hazards	7
4.3	Electrical and control system hazards	7
4.3.1	Electrical hazards	7
4.3.2	Control system hazards	7
4.4	Thermal hazards	8
4.5	Fire hazards	8
4.6	Noise hazards	8
4.7	Hazards caused by gases, vapours, fumes and dusts	8
4.8	Hazards generated by neglecting ergonomic principles in machinery design	8
4.9	Hazards during the setting mode	9
4.10	Falls from heights	9
4.11	Hazards related to cold-chamber die casting machines	9
4.11.1	Bursting of biscuits	9
4.11.2	Injection drive area	9
4.12	Hazards related to hot-chamber die casting machines	9
4.12.1	Nozzle	9
4.12.2	Initiation of the casting process due to a fault in the control system	9
4.13	Hazards due to hydraulics and pneumatics	9
5	Safety requirements and/or protective measures	10
5.1	General	10
5.2	Mechanical	10
5.2.1	General	10
5.2.2	Guards and protective devices for the die area	10
5.2.3	Access to the die closing mechanism area	12
5.2.4	Additional requirements for movable guards and access doors	12
5.2.5	Die casting units	13
5.3	Electric equipment and control systems	14
5.3.1	Electric equipment	14
5.3.2	Safety related parts of the control system: General	14
5.3.3	Emergency stop functions	14
5.3.4	Safety related control system of the dangerous movements of the die	14
5.3.5	Control of ancillary equipment	15
5.4	Measures against thermal hazards	16
5.4.1	Spurting of molten metal	16
5.4.2	Contact with hot surfaces	16
5.5	Hydraulics, pneumatics and combustible fluids	16
5.5.1	Hydraulics, pneumatics	16
5.5.2	Pressure fluids	16
5.5.3	Spray systems for release agents	16

5.6	Noise	17
5.6.1	Noise reduction as a safety requirement	17
5.6.2	Noise emission measurement and declaration on die casting machines	17
5.6.3	Noise test code	17
5.7	Gases, vapours, fumes and dusts	19
5.8	Ergonomic aspects	19
5.9	Protective measures when setting-up of die casting machines, inserting and removing appliances, tie bar pulling devices and other ancillary equipment	19
5.9.1	Setting-up without protective devices for the die area	19
5.9.2	Movement of core pullers and ejectors	20
5.9.3	Movement of tie bars	20
5.9.4	Movement of the plunger of cold-chamber machines	20
5.10	Elevated working places	20
5.11	Additional protective measures for cold-chamber die casting machines	21
5.11.1	Bursting and removal of biscuit	21
5.11.2	Guards and protective devices for the injection area	21
5.12	Additional protective measures for hot-chamber die casting machines	21
5.12.1	Metal splashing	21
5.12.2	Movement of the injection piston	21
6	Verification of the safety requirements and/or protective measures	22
7	Information for use	23
7.1	General	23
7.2	Warning devices and safety signs	23
7.3	Accompanying documents	23
7.3.1	Instruction handbook	23
7.4	Marking	25
Annex A (informative)	Examples	27
Annex B (normative)	Requirements for the European Union and associated countries	40
Annex C (normative)	Requirements for China (noise test code)	41
Bibliography	42