

DIN EN 869:2007-02 (E)

Safety of machinery - Safety requirements for pressure metal diecasting units

Contents		Page
Foreword		5
Introduction		6
1	Scope	6
2	Normative references	6
3	Terms and definitions	8
4	List of significant hazards	11
4.1	General	11
4.2	Mechanical hazards	11
4.3	Electrical hazards/control system	12
4.4	Thermal hazards	12
4.5	Fire hazards	12
4.6	Noise hazards	13
4.7	Hazards caused by gases, vapours, fumes and dusts	13
4.8	Hazards generated by neglecting ergonomic principles in machinery design	13
4.9	Setting-up the diecasting machine	14
4.10	Falls from heights	14
4.11	Particular hazards with regard to cold-chamber diecasting machines	14
4.11.1	Bursting of slugs	14
4.11.2	Injection drive area	14
4.12	Particular hazards of diecasting machines with vertical closing movement	14
4.13	Particular hazards with regard to hot-chamber diecasting machines	14
4.13.1	Nozzle	14
4.13.2	Initiation of the casting process due to a fault in the control system	14
4.14	Hydraulics and pneumatics	14
5	Safety requirements and/or protective measures	14
5.1	General	14
5.2	Mechanical	15
5.2.1	General	15
5.2.2	Guards and protective devices for die area (see also 5.4.1)	15
5.2.3	Guards for the die closing mechanism area	17
5.2.4	Additional requirements for movable guards and access doors	17
5.2.5	Diecasting units	18
5.3	Electric equipment and control systems	18
5.3.1	Electric equipment	18
5.3.2	Safety related parts of the control system: General	18
5.3.3	Emergency stop functions	19
5.3.4	Safety related control system of the dangerous movements of the die	19
5.3.5	Safety related control system of the dangerous movements with closing safety device	19
5.3.6	Control of ancillary equipment	20
5.4	Measures against thermal hazards	20
5.4.1	Spurting of molten metal	20
5.4.2	Contact with hot surfaces	20
5.5	Hydraulics, pneumatics, combustible fluids	20
5.5.1	Hydraulics, pneumatics	20
5.5.2	Pressure fluids	20
5.5.3	Spray systems for release agents	20

5.5.4	Heat exchanger media	20
5.6	Noise	21
5.6.1	Noise sources	21
5.6.2	Noise reduction as a safety requirement	21
5.6.3	Noise emission measurement and declaration	21
5.7	Gases, vapours, fumes and dusts	21
5.8	Ergonomic aspects	22
5.9	Protective measures when setting-up diecasting machines, inserting and removal appliances, tie bar pulling devices, and other ancillary equipment	22
5.9.1	Setting-up without protective devices for the die area	22
5.9.2	Movement of core pullers and ejectors	22
5.9.3	Movement of tie bar pulling devices	22
5.9.4	Movement of the plunger of cold chamber machines	22
5.10	Elevated working places	23
5.11	Additional protective measures for cold-chamber diecasting machines	23
5.11.1	Bursting and removal of slugs	23
5.11.2	Guards for the plunger area with vertical shot sleeve	23
5.11.3	Guards for the plunger area with horizontal shot sleeve	23
5.12	Additional protective measures for diecasting machines with vertical closing movement	23
5.13	Additional protective measures for hot-chamber diecasting machines	23
5.13.1	Metal spraying between nozzle and die	23
5.13.2	Movement of the injection piston	24
6	Verification of the safety requirements and/or protective measures	24
7	Information for use	25
7.1	General	25
7.2	Signals and warning devices	25
7.3	Accompanying documents	25
7.3.1	Instruction handbook	25
7.4	Marking	28
Annex A (informative) Examples		29
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC		41
Bibliography		42
Figure A.1 -- Example of a hot chamber diecasting machine (can be manufactured with a horizontal or a vertical die closing system)		29
Figure A.2 -- Example of a horizontal cold-chamber diecasting machine (can be manufactured with a horizontal or a vertical die closing system)		29
Figure A.3 -- Example of a vertical cold-chamber diecasting machine with vertical shot-end (can be manufactured with a horizontal or a vertical die closing system)		30
Figure A.4 -- Examples of mechanical hazards and danger zones		30
Figure A.5 -- Examples of danger zones for metal spraying at horizontal cold-chamber machines ...		31
Figure A.6 -- Examples of danger zones for metal spraying at vertical cold-chamber machines with vertical shot-end		31
Figure A.7 -- Examples of danger zones for metal spraying at hot-chamber machines		32
Figure A.8 -- Distance between the guard and machine frame according to 5.2.2.1		32
Figure A.9 -- Example of guarding the hazardous area of a diecasting cell		33

Figure A.10 -- Example for a closing safety device with positively actuated hydraulic valve, see 5.3.5.1 a)	34
Figure A.11 -- Example for a closing safety device with positively actuated pilot valve, see 5.3.5.1 b)	35
Figure A.12 -- Example for a closing safety device with positively actuated limit switch which drives the shut- off valve, see 5.3.5.1 c)	36
Figure A.13 -- Example for a closing safety device with positively actuated limit switch which drives a pilot valve, see 5.3.5.1 c)	37
Figure A.14 -- Example of safety related control system with closing safety device for closing units, see 5.3.5.1 d)	38
Figure A.15 -- Example of safety related control system with closing safety device for closing units, see 5.3.5.1 d)	39
Figure A.16 -- Example of additional requirements on the hydraulic control of machines with vertical closing movement against pressure peaks and gravity (for electrical interlocking and monitoring, see Figures A.10 to A.15	40
Tables Table 1 -- Methods of verification	24
Table 1 (continued)	25