

DIN EN 13042-1:2007-05 (Eng lisch)

Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 1: Gob feeder

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	6
4 List of significant hazards	6
5 Safety requirements and/or protective measures	7
5.1 General	7
5.2 Starting and stopping and unexpected start-up	8
5.3 Emergency-stop equipment	8
5.4 Avoiding slip hazard	8
5.5 Design of manual controls	8
5.6 Guards	8
5.7 Lockout of shears	9
5.8 Hydraulic/pneumatic system	9
5.9 Electrical equipment	9
5.10 Energy supply disconnecting devices	9
5.11 Gob-loading interruption	9
5.12 Quick release refractory chucks	9
5.13 Refractory lifting device	9
5.14 Glass flow	9
5.15 Necessary movements in case of power failure	10
5.16 Safeguarding against contact with hot surfaces	10
6 Verification of safety requirements and/or protective measures	10
7 Information for use	11
7.1 General	11
7.2 Accompanying documents (in particular: Instruction handbook)	11
7.3 Marking	11
Annex A (informative) Glossary	13
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	14
Bibliography	15
Tables Table 1 -- List of significant hazards	6
Table 2 -- Individual testing for requirements stated in Clause 5	10