

ISO 3548-3:2023-03 (E)

Plain bearings - Thin-walled half bearings with or without flange - Part 3: Determination of the peripheral length

Contents		Page
Foreword		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	2
5	Purpose of checking	4
6	Measurement methods	4
6.1	Method A	4
6.2	Method B	5
7	Choice and designation of checking method	6
7.1	Choice of checking method	6
7.2	Designation of checking method	7
8	Measuring equipment	7
9	Measuring equipment requirements	9
9.1	General	9
9.2	Tolerance on checking load setting	9
9.3	Speed of approach of measuring head	10
9.4	Construction of measuring head	10
9.5	Accuracy of the measuring plane for metering bars	10
9.6	Accuracy of the dial gauge	10
10	Gauging tools for establishing the datum	10
10.1	General	10
10.2	Master checking block (used alone)	11
10.3	Series checking block used alone	11
10.4	Series checking block with master shell	11
11	Checking block requirements	11
11.1	General	11
11.2	Reference tooling: Master checking block -- General	12
11.2.1	Reference tooling -- Master checking block	12
11.2.2	Manufacturing limits -- General	12
11.2.3	Measuring accuracy of equipment used for establishing dcbm,M and Hcbm,M	13
11.2.4	Permissible wear limit	14
11.3	Series gauging tools	14
11.3.1	Series checking block used alone	14
11.3.2	Manufacturing limits, correction factor and permissible wear limit	14
11.3.3	Series checking block with master shell or with comparison shell	16
12	Master shell and comparison shell requirements	16
12.1	Master shell requirements	16
12.1.1	Manufacturing limits	17

12.1.2	Correction factor, Fcor ms	18
12.1.3	Permissible wear limit	18
12.2	Comparison shell requirements	18
13	Correction factors	19
13.1	Reference tooling: Master checking block correction factor, Fcor cbm	19
13.2	Series control tooling	19
13.2.1	Correction factor for series checking block used alone, Fcor cbs	19
13.2.2	Correction factor for series checking block with master shell	19
13.2.3	Master shell correction factor, Fcor ms	19
13.2.4	Comparison shell correction factor, Fcor cs	20
13.3	Marking	20
13.4	Reference setting	20
14	Typical checking procedure	20
15	Conditions of the half bearings to be checked	21
16	Measuring errors	21
16.1	Errors due to measuring equipment	21
16.2	Errors due to the checking block	21
16.3	Errors due to the correction factor	22
16.4	Errors due to the half bearing	22
16.5	Error due to the choice of checking method	22
17	Accuracy of methods used	22
17.1	General	22
17.2	Checking conditions	22
17.3	Limits	22
17.4	Calculation	22
18	Specifications on bearing drawings	22
19	Specifications for the control of the checking means	23
Annex A	(normative) Determination of the correction factor of the master checking block -- Method A	24
Annex B	(normative) Determination of the correction factor of the master checking block -- Method B	29
Annex C	(normative) Determination of the correction factor of the series checking block used alone	33
Annex D	(normative) Determination of the correction factor of the master shell or comparison shell	35
Annex E	(normative) Tests and calculation of repeatability, reproducibility and comparability	37
Bibliography	40