

# ISO 19403-2:2024-09 (E)

## Paints and varnishes - Wettability - Part 2: Determination of the surface free energy of solid surfaces by measuring the contact angle

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Principle .....</b>	<b>1</b>
<b>5</b>	<b>Apparatus and materials .....</b>	<b>2</b>
<b>6</b>	<b>Sampling .....</b>	<b>3</b>
<b>7</b>	<b>Procedure .....</b>	<b>3</b>
7.1	General for measuring on the horizontal drop .....	3
7.1.1	Setting up the contact angle measuring system .....	3
7.1.2	Test conditions .....	4
7.1.3	Conditioning of the test panels .....	4
7.2	Measurement .....	4
7.2.1	General .....	4
7.2.2	Static method .....	4
7.2.3	Dynamic method (progressive contact angle) .....	5
7.2.4	Determination of the contact angle .....	6
<b>8</b>	<b>Evaluation .....</b>	<b>6</b>
8.1	General .....	6
8.2	Owens-Wendt-Rabel-Kaelble method (OWRK method) .....	6
8.3	Wu method .....	7
<b>9</b>	<b>Precision .....</b>	<b>8</b>
9.1	General .....	8
9.2	Repeatability limit, r .....	8
9.3	Reproducibility limit, R .....	8
9.4	Calculation in accordance with the Owens-Wendt-Rabel-Kaelble method .....	8
<b>10</b>	<b>Test report .....</b>	<b>9</b>
<b>Annex A (informative) Notes on measuring practice .....</b>		<b>10</b>
<b>Bibliography .....</b>		<b>14</b>