

DIN EN 869:2007-02 (E)

Safety of machinery - Safety requirements for pressure metal diecasting units

| Contents | | Page |
|--------------------|--|-------------|
| Foreword | | 5 |
| Introduction | | 6 |
| 1 | Scope | 6 |
| 2 | Normative references | 6 |
| 3 | Terms and definitions | 8 |
| 4 | List of significant hazards | 11 |
| 4.1 | General | 11 |
| 4.2 | Mechanical hazards | 11 |
| 4.3 | Electrical hazards/control system | 12 |
| 4.4 | Thermal hazards | 12 |
| 4.5 | Fire hazards | 12 |
| 4.6 | Noise hazards | 13 |
| 4.7 | Hazards caused by gases, vapours, fumes and dusts | 13 |
| 4.8 | Hazards generated by neglecting ergonomic principles in machinery design | 13 |
| 4.9 | Setting-up the diecasting machine | 14 |
| 4.10 | Falls from heights | 14 |
| 4.11 | Particular hazards with regard to cold-chamber diecasting machines | 14 |
| 4.11.1 | Bursting of slugs | 14 |
| 4.11.2 | Injection drive area | 14 |
| 4.12 | Particular hazards of diecasting machines with vertical closing movement | 14 |
| 4.13 | Particular hazards with regard to hot-chamber diecasting machines | 14 |
| 4.13.1 | Nozzle | 14 |
| 4.13.2 | Initiation of the casting process due to a fault in the control system | 14 |
| 4.14 | Hydraulics and pneumatics | 14 |
| 5 | Safety requirements and/or protective measures | 14 |
| 5.1 | General | 14 |
| 5.2 | Mechanical | 15 |
| 5.2.1 | General | 15 |
| 5.2.2 | Guards and protective devices for die area (see also 5.4.1) | 15 |
| 5.2.3 | Guards for the die closing mechanism area | 17 |
| 5.2.4 | Additional requirements for movable guards and access doors | 17 |
| 5.2.5 | Diecasting units | 18 |
| 5.3 | Electric equipment and control systems | 18 |
| 5.3.1 | Electric equipment | 18 |
| 5.3.2 | Safety related parts of the control system: General | 18 |
| 5.3.3 | Emergency stop functions | 19 |
| 5.3.4 | Safety related control system of the dangerous movements of the die | 19 |
| 5.3.5 | Safety related control system of the dangerous movements with closing safety device | 19 |
| 5.3.6 | Control of ancillary equipment | 20 |
| 5.4 | Measures against thermal hazards | 20 |
| 5.4.1 | Spurting of molten metal | 20 |
| 5.4.2 | Contact with hot surfaces | 20 |
| 5.5 | Hydraulics, pneumatics, combustible fluids | 20 |
| 5.5.1 | Hydraulics, pneumatics | 20 |
| 5.5.2 | Pressure fluids | 20 |
| 5.5.3 | Spray systems for release agents | 20 |

| | | |
|--|--|----|
| 5.5.4 | Heat exchanger media | 20 |
| 5.6 | Noise | 21 |
| 5.6.1 | Noise sources | 21 |
| 5.6.2 | Noise reduction as a safety requirement | 21 |
| 5.6.3 | Noise emission measurement and declaration | 21 |
| 5.7 | Gases, vapours, fumes and dusts | 21 |
| 5.8 | Ergonomic aspects | 22 |
| 5.9 | Protective measures when setting-up diecasting machines, inserting and removal appliances, tie bar pulling devices, and other ancillary equipment | 22 |
| 5.9.1 | Setting-up without protective devices for the die area | 22 |
| 5.9.2 | Movement of core pullers and ejectors | 22 |
| 5.9.3 | Movement of tie bar pulling devices | 22 |
| 5.9.4 | Movement of the plunger of cold chamber machines | 22 |
| 5.10 | Elevated working places | 23 |
| 5.11 | Additional protective measures for cold-chamber diecasting machines | 23 |
| 5.11.1 | Bursting and removal of slugs | 23 |
| 5.11.2 | Guards for the plunger area with vertical shot sleeve | 23 |
| 5.11.3 | Guards for the plunger area with horizontal shot sleeve | 23 |
| 5.12 | Additional protective measures for diecasting machines with vertical closing movement | 23 |
| 5.13 | Additional protective measures for hot-chamber diecasting machines | 23 |
| 5.13.1 | Metal spraying between nozzle and die | 23 |
| 5.13.2 | Movement of the injection piston | 24 |
| 6 | Verification of the safety requirements and/or protective measures | 24 |
| 7 | Information for use | 25 |
| 7.1 | General | 25 |
| 7.2 | Signals and warning devices | 25 |
| 7.3 | Accompanying documents | 25 |
| 7.3.1 | Instruction handbook | 25 |
| 7.4 | Marking | 28 |
| Annex A (informative) Examples | | 29 |
| Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC | | 41 |
| Bibliography | | 42 |
| Figure A.1 -- Example of a hot chamber diecasting machine (can be manufactured with a horizontal or a vertical die closing system) | | 29 |
| Figure A.2 -- Example of a horizontal cold-chamber diecasting machine (can be manufactured with a horizontal or a vertical die closing system) | | 29 |
| Figure A.3 -- Example of a vertical cold-chamber diecasting machine with vertical shot-end (can be manufactured with a horizontal or a vertical die closing system) | | 30 |
| Figure A.4 -- Examples of mechanical hazards and danger zones | | 30 |
| Figure A.5 -- Examples of danger zones for metal spraying at horizontal cold-chamber machines ... | | 31 |
| Figure A.6 -- Examples of danger zones for metal spraying at vertical cold-chamber machines with vertical shot-end | | 31 |
| Figure A.7 -- Examples of danger zones for metal spraying at hot-chamber machines | | 32 |
| Figure A.8 -- Distance between the guard and machine frame according to 5.2.2.1 | | 32 |
| Figure A.9 -- Example of guarding the hazardous area of a diecasting cell | | 33 |

| | |
|---|-----------|
| Figure A.10 -- Example for a closing safety device with positively actuated hydraulic valve, see 5.3.5.1 a) | 34 |
| Figure A.11 -- Example for a closing safety device with positively actuated pilot valve, see 5.3.5.1 b) | 35 |
| Figure A.12 -- Example for a closing safety device with positively actuated limit switch which drives the shut- off valve, see 5.3.5.1 c) | 36 |
| Figure A.13 -- Example for a closing safety device with positively actuated limit switch which drives a pilot valve, see 5.3.5.1 c) | 37 |
| Figure A.14 -- Example of safety related control system with closing safety device for closing units, see 5.3.5.1 d) | 38 |
| Figure A.15 -- Example of safety related control system with closing safety device for closing units, see 5.3.5.1 d) | 39 |
| Figure A.16 -- Example of additional requirements on the hydraulic control of machines with vertical closing movement against pressure peaks and gravity (for electrical interlocking and monitoring, see Figures A.10 to A.15 | 40 |
| Tables Table 1 -- Methods of verification | 24 |
| Table 1 (continued) | 25 |