

# DIN EN 13890:2010-01 (E)

## Workplace exposure - Procedures for measuring metals and metalloids in airborne particles - Requirements and test methods

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Principle .....	6
5	Requirements .....	6
5.1	Method description .....	6
5.2	Performance requirements .....	7
6	Reagents and materials .....	8
6.1	Reagents .....	8
6.2	Standard solutions .....	8
6.3	Test materials .....	9
6.4	Reference air samples .....	9
7	Apparatus .....	9
8	Test methods .....	9
8.1	Detection limits and quantification limits .....	9
8.2	Analytical recovery .....	10
8.3	Measurement uncertainty .....	12
9	Test report .....	13
Annex A (informative) Guidance on determination of analytical recovery .....		14
Annex B (informative) Estimation of uncertainty of measurement .....		16
Annex C (informative) Interpolation of standard deviation .....		35
Annex D (informative) Example of estimation of expanded uncertainty .....		37
Bibliography .....		40