

# DIN EN 1076:2010-04 (E)

## Workplace exposure - Procedures for measuring gases and vapours using pumped samplers - Requirements and test methods

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Symbols and abbreviated terms .....	5
5	Types of samplers .....	7
6	Requirements .....	7
6.1	General .....	7
6.2	Sampler requirements .....	7
6.3	Measuring procedure requirements .....	10
7	General test conditions .....	12
7.1	Reagents .....	12
7.2	Apparatus .....	12
7.3	Independent method .....	13
7.4	Generation of the calibration gas mixture .....	13
8	Test methods .....	14
8.1	General .....	14
8.2	Sampler test methods .....	14
8.3	Measuring procedure test methods .....	15
8.4	Uncertainty of measurement .....	22
9	Test report .....	23
Annex A (informative) Examples for the determination of the breakthrough volume .....		24
A.1	Direct method .....	24
A.2	Chromatographic method .....	24
Annex B (informative) Estimation of uncertainty of measurement .....		26
B.1	General .....	26
B.2	Uncertainty associated with sampled air volume .....	26
B.3	Uncertainty associated with sampling efficiency .....	28
B.4	Uncertainty associated with sample storage and transportation .....	28
B.5	Uncertainty associated with method recovery .....	28
B.6	Uncertainty associated with method variability .....	32
B.7	Calculation of combined standard uncertainty .....	35
Annex C (informative) Example of estimation of expanded uncertainty .....		37
Bibliography .....		41