

# ISO 7870-6:2024-07 (E)

## Control charts - Part 6: EWMA control charts for the process mean

---

<b>Contents</b>		<b>Page</b>
Foreword		iv
Introduction		v
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>1</b>
<b>4</b>	<b>Symbols and abbreviated terms</b>	<b>2</b>
<b>5</b>	<b>EWMA for inspection by variables</b>	<b>3</b>
5.1	General	3
5.2	Weighted average explained	3
5.3	Control limits for EWMA control chart	4
5.4	Construction of EWMA control chart	5
5.5	Example	7
<b>6</b>	<b>Choice of the control chart</b>	<b>10</b>
6.1	Shewhart control chart versus EWMA control chart	10
6.2	Average run length	11
6.3	Choice of parameters for EWMA control chart	11
6.3.1	Choice of $\lambda$	11
6.3.2	Choice of $L_z$	12
6.3.3	Calculation for $n$	12
6.3.4	Example	13
<b>7</b>	<b>Procedure for implementing the EWMA control chart</b>	<b>13</b>
<b>8</b>	<b>Sensitivity of the EWMA to non-normality</b>	<b>14</b>
<b>9</b>	<b>Advantages and limitations</b>	<b>14</b>
9.1	Advantages	14
9.2	Limitations	14
<b>Annex A (informative)</b>	<b>Application of the EWMA control chart</b>	<b>16</b>
<b>Annex B (informative)</b>	<b>EWMA control chart for a proportion of nonconforming items</b>	<b>20</b>
<b>Annex C (informative)</b>	<b>EWMA control charts for a number of nonconformities</b>	<b>22</b>
<b>Bibliography</b>		<b>24</b>