ISO 4765:2022-04 (E)

Chemically- induced ultra-weak photon emission (UPE) - Measurement as ananalysis method of degradation of polymeric material

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Measurement principle and its limitations 2

5 Sample 2

6 UPE measuring apparatus 3
6.1 Composition of UPE apparatus body 3
6.2 Composition of sample chamber 3
6.3 Installation environment for UPE apparatus 4
6.4 Sensitivity check 4

7 Measurement method 5
7.1 UPE apparatus preparation 5
7.2 Confirmation of normal operation of UPE apparatus 5
7.3 Measurement procedure 5
7.3.1 Setting of measurement condition 5
7.3.2 Measurement of background 6
7.3.3 Sample measurement 6

8 Display of measurement results 7
8.1 General 7
8.2 Measurement in inert gas atmosphere 7
8.3 Measurement in oxidation accelerating atmosphere 8

9 Test report 10

Annex A (informative) Detection of oxidation deterioration by UPE measurement 11

AnnexB(informative)ExamplesoftimecoursesofUPEofthermallyoxidizedpolypropylene (PP) for isothermal and non-isothermal measurement 16

Annex C (informative) Example of measurements of oxidation deterioration degree of thermally oxidized polyethylene (PE) 18

Annex D (informative) Example evaluation of oxidation induction time (OIT) 20

Annex E (informative) Example of UPE of PP oxidized by accelerated weathering test 22

Bibliography 26