ISO 16474-4:2013-11 (E)

Paints and varnishes - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2

5 Apparatus 2
5.1 Laboratory light source 2
5.2 Test chamber 6
5.3 Radiometer 6
5.4 Black-standard/black-panel thermometer 6
5.5 Wetting and humidity-control equipment 6
5.6 Specimen holders 7
5.7 Apparatus to assess changes in properties 7

6 Test specimens 7

7 Exposure conditions 7
7.1 Temperature 7
7.2 Relative humidity of chamber air 8
7.3 Spray cycle 8

8 Procedure 8
8.1 General 8
8.2 Mounting the test specimens 8
8.3 Exposure 8
8.4 Duration of test 9
8.5 Measurement of radiant exposure 9
8.6 Determination of changes in properties after exposure 9

9 Test report 9

Bibliography 10