ISO/TS 5660-3:2012-12 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 3: Guidance on measurement

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Capability and limitations of the cone calorimeter 1

4 Calibration of the cone calorimeter 2
4.1 General 2
4.2 Heat flux meter calibration (see 6.12 and 10.3.1 of ISO 5660-1:2002) 2
4.3 Calibration frequency 2
4.4 Oxygen analyser calibration (see 10.1.5, 10.1.6 and 10.2.3 of ISO 5660-1:2002) 3
4.5 Determining orifice plate calibration factor 4
4.6 Additional comments on the orifice calibration factor 4
4.7 Calibration of smoke measurement system 5
4.8 Precautions in relation to water/CO2 removal 6
4.9 Routine maintenance 6

5 Test specimen preparation and presentation 6
5.1 General 6
5.2 Specimen trays and edge retainer frame 8

6 Selection of heat flux 9

7 Ignition protocols 11

8 Guidance on the testing of non-standard products 11
8.1 General 11
8.2 Non-planar products 11
8.3 Radiation transfer considerations 13
8.4 Thermally mobile specimens 19

9 Composites and layered products 20
9.1 General 20
9.2 Non-homogeneous products 20
9.3 Specimens with short test duration 20

10 Liquids 21
10.1 General 21
10.2 Testing without the radiant heater 21
10.3 Testing with the radiant heater 22

11 The theory of oxygen consumption calorimetry 22
11.1 General 22
11.2 Silicones 23
11.3 Effect of additives and fillers 24

12 Start and end of test 25

12.1 Start of test 25
12.2 End of test 25

13 Recommendations for presentation of data 25
13.1 Current situation 25
13.2 Additional useful data 26
13.3 Recommendations 29

Annex A (informative) Predictive methods from ISO 5660-1 data 30

Annex B (informative) Effect of additives and fillers 37

Annex C (informative) Measurements at low levels of heat release 40

Bibliography 42