DIN EN 13890:2010-01 (E)

Workplace exposure - Procedures for measuring metals and metalloids in airborne particles - Requirements and test methods

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Principle 6

5 Requirements 6
5.1 Method description 6
5.2 Performance requirements 7

6 Reagents and materials 8
6.1 Reagents 8
6.2 Standard solutions 8
6.3 Test materials 9
6.4 Reference air samples 9

7 Apparatus 9

8 Test methods 9
8.1 Detection limits and quantification limits 9
8.2 Analytical recovery 10
8.3 Measurement uncertainty 12

9 Test report 13

Annex A (informative) Guidance on determination of analytical recovery 14

Annex B (informative) Estimation of uncertainty of measurement 16

Annex C (informative) Interpolation of standard deviation 35

Annex D (informative) Example of estimation of expanded uncertainty 37

Bibliography 40