DIN EN 1076:2010-04 (E)

Workplace exposure - Procedures for measuring gases and vapours using pumped samplers - Requirements and test methods

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Symbols and abbreviated terms 5

5 Types of samplers 7

6 Requirements 7
6.1 General 7
6.2 Sampler requirements 7
6.3 Measuring procedure requirements 10

7 General test conditions 12
7.1 Reagents 12
7.2 Apparatus 12
7.3 Independent method 13
7.4 Generation of the calibration gas mixture 13

8 Test methods 14
8.1 General 14
8.2 Sampler test methods 14
8.3 Measuring procedure test methods 15
8.4 Uncertainty of measurement 22

9 Test report 23

Annex A (informative) Examples for the determination of the breakthrough volume 24

A.1 Direct method 24
A.2 Chromatographic method 24

Annex B (informative) Estimation of uncertainty of measurement 26

B.1 General 26
B.2 Uncertainty associated with sampled air volume 26
B.3 Uncertainty associated with sampling efficiency 28
B.4 Uncertainty associated with sample storage and transportation 28
B.5 Uncertainty associated with method recovery 28
B.6 Uncertainty associated with method variability 32
B.7 Calculation of combined standard uncertainty 35

Annex C (informative) Example of estimation of expanded uncertainty 37

Bibliography 41