DIN EN 838:2010-05 (E)

Workplace exposure - Procedures for measuring gases and vapours using diffusive samplers - Requirements and test methods

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Symbols and abbreviations 5

5 Types of samplers 7

6 Requirements 7
6.1 General 7
6.2 Sampler requirements 8
6.3 Measuring procedure requirements 9

7 General test conditions 11
7.1 Reagents 11
7.2 Apparatus 11
7.3 Independent method 12
7.4 Generation of a calibration gas mixture 12

8 Test methods 13
8.1 General 13
8.2 Sampler test methods 13
8.3 Measuring procedure test methods 16
8.4 Uncertainty of measurement 21

9 Test report 23

Annex A (informative) Fundamentals of diffusive sampling 24

Annex B (informative) Estimation of uncertainty of measurement 26

Annex C (informative) Example of estimation of expanded uncertainty 36

Bibliography 39