ISO 3548-3:2023-03 (E)

Plain bearings - Thin-walled half bearings with or without flange - Part 3: Determination of the peripheral length

Contents

Page

Foreword v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols 2

5 Purpose of checking 4

6 Measurement methods 4
6.1 Method A 4
6.2 Method B 5

7 Choice and designation of checking method 6
7.1 Choice of checking method 6
7.2 Designation of checking method 7

8 Measuring equipment 7

9 Measuring equipment requirements 9
9.1 General 9
9.2 Tolerance on checking load setting 9
9.3 Speed of approach of measuring head 10
9.4 Construction of measuring head 10
9.5 Accuracy of the measuring plane for metering bars 10
9.6 Accuracy of the dial gauge 10

10 Gauging tools for establishing the datum 10
10.1 General 10
10.2 Master checking block (used alone) 11
10.3 Series checking block used alone 11
10.4 Series checking block with master shell 11

11 Checking block requirements 11
11.1 General 11
11.2 Reference tooling: Master checking block -- General 12
11.2.1 Reference tooling -- Master checking block 12
11.2.2 Manufacturing limits -- General 12
11.2.3 Measuring accuracy of equipment used for establishing dcbm,M and Hcbm,M 13
11.2.4 Permissible wear limit 14
11.3 Series gauging tools 14
11.3.1 Series checking block used alone 14
11.3.2 Manufacturing limits, correction factor and permissible wear limit 14
11.3.3 Series checking block with master shell or with comparison shell 16

12 Master shell and comparison shell requirements 16
12.1 Master shell requirements 16
12.1.1 Manufacturing limits 17

12.1.2 Correction factor, Fcor ms 18
12.1.3 Permissible wear limit 18
12.2 Comparison shell requirements 18

13 Correction factors 19
13.1 Reference tooling: Master checking block correction factor, Fcor cbm 19
13.2 Series control tooling 19
13.2.1 Correction factor for series checking block used alone, Fcor cbs 19
13.2.2 Correction factor for series checking block with master shell 19
13.2.3 Master shell correction factor, Fcor ms 19
13.2.4 Comparison shell correction factor, Fcor cs 20
13.3 Marking 20
13.4 Reference setting 20

14 Typical checking procedure 20

15 Conditions of the half bearings to be checked 21

16 Measuring errors 21
16.1 Errors due to measuring equipment 21
16.2 Errors due to the checking block 21
16.3 Errors due to the correction factor 22
16.4 Errors due to the half bearing 22
16.5 Error due to the choice of checking method 22

17 Accuracy of methods used 22
17.1 General 22
17.2 Checking conditions 22
17.3 Limits 22
17.4 Calculation 22

18 Specifications on bearing drawings 22

19 Specifications for the control of the checking means 23

Annex A (normative) Determination of the correction factor of the master checking block -- Method A 24

Annex B (normative) Determination of the correction factor of the master checking block -- Method B 29

Annex C (normative) Determination of the correction factor of the series checking block used alone 33

Annex D (normative) Determination of the correction factor of the master shell or comparison shell 35

Annex E (normative) Tests and calculation of repeatability, reproducibility and comparability 37

Bibliography 40