ISO 7481:2023-11 (E)

Aerospace - Nuts, self-locking, with maximum operating temperature less than or equal to 425 °C - Test methods

Contents

Page

Foreword ..... **iv**

1 Scope **1**

2 Normative references **1**

3 Terms and definitions **1**

4 Inspections and tests **1**

4.1 Hardness test 1
4.1.1 Procedure 1
4.1.2 Method 2
4.2 Bearing surface squareness test 2
4.2.1 Test device 2
4.2.2 Method 3
4.3 Axial load test 4
4.3.1 Test device 4
4.3.2 Method 4
4.4 Wrenching feature test 6
4.4.1 General 6
4.4.2 Test device 6
4.4.3 Method 7
4.5 Stress embrittlement test 7
4.5.1 General 7
4.5.2 Test device 7
4.5.3 Method 7
4.6 Torque-out test 8
4.6.1 General 8
4.6.2 Test device 9
4.6.3 Method 9
4.7 Test of no rotation of the captive washer 9
4.7.1 General 9
4.7.2 Test device 10
4.7.3 Method 10
4.8 Push-out test 10
4.8.1 General 10
4.8.2 Test device 10
4.8.3 Method 11
4.9 Self-locking torque at ambient temperature 12
4.9.1 Test device 12
4.9.2 Method 12
4.10 Self-locking torque at ambient temperature after heat soak at maximum operating temperature 14
4.10.1 Test device 14
4.10.2 Method 14
4.11 Permanent set test 15
4.11.1 General 15
4.11.2 Test device 15
4.11.3 Method 15
4.12 Vibration test 16
4.12.1 General 16
4.12.2 Test device 16
4.12.3 Method 18