ISO 20903:2011-11 (E)

Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Methods used to determine peak intensities and information required when reporting results

Contents

Page

Foreword ... iv

Introduction ... v

1 Scope ... 1

2 Normative references ... 1

3 Terms and definitions ... 1

4 Symbols and abbreviated terms ... 1

5 Methods for peakintensity determination -- Direct spectrum ... 1
5.1 General ... 1
5.2 Selection and subtraction of an inelastic background ... 3
5.3 Measurement of peak intensity ... 3
5.4 Measurement of a peak intensity with computer software ... 4
5.5 Measurement of peak intensities for a spectrum with overlapping peaks ... 5
5.6 Uncertainty in measurement of peak area ... 5

6 Methods for peak intensity determination -- Augerelectron differential spectrum ... 6
6.1 General ... 6
6.2 Measurement of Augerelectron differential intensity ... 6
6.3 Uncertainties in measurement of Augerelectron differential intensity ... 7

7 Reporting of methods used to measure peak intensities ... 8
7.1 General requirements ... 8
7.2 Methods used to determine peak intensities in direct spectra ... 8
7.3 Methods used to obtain and determine peak intensities in Augerelectron differential spectra ... 9

Annex A (informative) Instrumental effects on measured intensities ... 10

Annex B (informative) Useful integration limits for determination of peak intensities in XPS spectra ... 11

Bibliography ... 13