DIN 25457-1:2014-12 (E)

Activity measurement methods for the clearance of radioactive substances and nuclear faci lity components - Part 1: Fundamentals

Contents

Page

Foreword ... 5

1 Scope ... 6

2 Normative references ... 6

3 Terms, definitions and symbols ... 7
3.1 Terms and definitions ... 7
3.2 Symbols ... 9

4 Measurement methods ... 13
4.1 Basic model and characteristic variables of the activity measurement methods with consideration of type A and type B measuring uncertainties ... 13
4.1.1 General information ... 13
4.1.2 Description of the model in general form ... 14
4.1.3 Special model approach for activity measurement method ... 15
4.1.4 Procedure for conservative and realistic approaches ... 17
4.2 Direct surface-total-activity measurement ... 18
4.2.1 General ... 18
4.2.2 Relevant type B measurement uncertainties ... 19
4.2.3 Requirements for the measurement devices ... 20
4.2.4 Requirements for the calibration sources ... 20
4.2.5 State of the surface of the measured material ... 21
4.2.6 Dependency of the count rate of the detector on the geometric conditions ... 21
4.2.7 Determination of an alarm value ... 21
4.2.8 Measurement procedure ... 23
4.2.9 Quality assurance ... 25
4.3 Indirect surface total-activity measurement ... 26
4.3.1 General ... 26
4.3.2 Relevant type B measurement uncertainties ... 26
4.3.3 Requirements for the measurement setup ... 27
4.3.4 Requirements for the calibration source ... 27
4.3.5 Calibration ... 27
4.3.6 Background effect determination ... 27
4.3.7 Performing the measurement ... 27
4.3.8 Quality assurance ... 28
4.4 Spectrometric measurement methods ... 29
4.4.1 Gamma spectrometry on material samples ... 29
4.4.2 In-situ gamma spectrometry ... 36
4.4.3 Alpha spectrometry on material samples ... 42
4.4.4 Determination of the activity of alpha-emitting radionuclides using gamma spectrometry on material samples ... 47
4.5 Total gamma activity measurement ... 47
4.5.1 General ... 47
4.5.2 Relevant measurement uncertainties ... 48
4.5.3 Requirements for measurement equipment ... 48
4.5.4 Property of the measured material ... 48
4.5.5 Requirements for the calibration ... 48
4.5.6 Performing the measurement ... 49
4.5.7 Detection limit, decision threshold and confidence interval ... 49
4.5.8 Quality assurance ... 50

Annex A (normative) Determination of the surface response **52**

Annex B (informative) Energies and range of alpha particles **57**

Annex C (informative) Determination of the activity of alpha-emitting radionuclides using gamma spectrometry on material specimens **59**
C.1 General **59**
C.2 Thorium decay series and Th-230 ..... **59**
C.3 Uranium **59**
C.4 Plutonium **60**

Annex D (informative) Explanations for the calculation of the decision thresholds and detection limits for the pulse counting with time preselection **64**

Annex E (informative) Explanations for the calculation of the detection limit and decision threshold for stationary pulse rate measurements **69**

Annex F (informative) Explanations for the calculation of the detection limit and decision threshold for dynamic pulse rate measurement **79**

Annex G (informative) Explanations for the calculation of the decision thresholds and detection limits for the pulse counting with time preselection at small pulse numbers, e.g. alpha surface activity measurement **82**

Annex H (informative) Calculation of the detection limit and decision threshold, the upper limit of the confidence interval and the expected value for measurements using contamination monitors with consideration of type B measurement uncertainties **84**
H.1 Basic measurement model **84**
H.2 Measurement task and measurement parameters **85**
H.3 Calculation of the characteristic variables **86**
H.4 Interpretation of the results in respect of the decision measurement for the clearance **87**
H.5 Integration of uncertainties in respect of the clearance level of the area-specific total activity **88**

Annex I (informative) Calculation of the detection limit and decision threshold for measurements with wipe test measurement setups (indirect total surface activity measurement) **89**

Annex J (informative) Calculation of the detection limit and decision threshold, the upper limit of the confidence interval and the expected value for gamma spectrometry and in-situ gamma spectrometry **92**
J.1 Preliminary remarks **92**
J.2 Measurement of site grounds according to DIN 25457-7: Determination of the area-specific activity as well as the nuclide-specific dose rate of Cs-137 ..... **92**
J.2.1 General **92**
J.2.2 Calibration factor and its standard uncertainty **93**
J.2.3 Calculation of the nuclide-specific ambient dose equivalent rate **93**
J.2.4 Example for the calculation of the characteristic limits as well as the best estimator and its standard uncertainty (non-collimated measurement, area-specific activity and nuclide-specific dose rate) **94**
J.2.5 Summary **96**
J.3 Determination of the mass-specific activity if a disturbance is present due to an interfering line as well as a line in the background effect spectrum **96**
J.4 Determination of the Co-60 activity from very small net peak areas **98**

Annex K (informative) Calculation of the detection limit and the decision threshold, the upper limit of the confidence interval and the expected value for total gamma activity measurements **104**
K.1 Preliminary remarks **104**
K.2 Essential input variables for the conservative calibration **105**
K.3 Realistic calculation of decision threshold and detection limit **108**
K.3.1 General **108**
K.3.2 Determination of the realistic calibration factor *w* **108**
K.3.3 Consideration of the reduction of the background effect due to measured material **108**
K.3.4 Consideration of the non-counting statistical variance of the background effect **108**
K.4 Best estimated values, upper limit of the confidence interval **111**
K.5 Summary **114**

Bibliography **116**