ISO 12106:2017-03 (E)

Metallic materials - Fatigue testing - Axial-strain-controlled method

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Symbols 3
4.1 Specimens 3
4.2 Fatigue testing 3
4.2.1 Symbols 3
4.2.2 Subscripts 5
4.3 Expression of results 5

5 Apparatus 5
5.1 Test machine 5
5.1.1 General 5
5.1.2 Force transducer 6
5.1.3 Gripping of specimen 6
5.1.4 Alignment check 6
5.2 Strain measurement 7
5.3 Heating device and temperature measurement 8
5.4 Instrumentation for test monitoring 8
5.4.1 Recording systems 8
5.4.2 Cycle counter 9
5.5 Checking and verification 9

6 Specimens 9
6.1 Geometry 9
6.1.1 Round bars 9
6.1.2 Flat sheet products 10
6.2 Preparation of specimens 14
6.2.1 General 14
6.2.2 Machining procedure 14
6.2.3 Sampling and marking 15
6.2.4 Surface condition of specimen 15
6.2.5 Dimensional check 16
6.2.6 Storage and handling 16

7 Procedure 16
7.1 Laboratory environment 16
7.2 Test machine control 16
7.3 Mounting of the specimen 17
7.4 Cycle shape -- Strain rate or frequency of cycling 17
7.5 Start of test 18
7.5.1 Preliminary measurements 18
7.5.2 Test commencement 19
7.6 Number of specimens 19
7.7 Data recording 19

7.7.1 Stress-strain hysteresis loops 19
7.7.2 Data acquisition 19
7.8 End of test 20
7.9 Failure criteria 20

8 High-temperature strain-controlled creep-fatigue testing 22

9 Expression of results 23
9.1 Basic data (recorded data (see 7.7)) 23
9.2 Analysis of low-cycle fatigue results at Re = -1 23
9.2.1 Distinction between different types of strain values 23
9.2.2 Determination of fatigue life (see 7.9) 24
9.2.3 Stress-strain and strain-fatigue life relationships 24
9.3 Analysis of creep-fatigue results 25

10 Test report 25
10.1 General 25
10.2 Purpose of the test 26
10.3 Material 26
10.4 Specimen 26
10.5 Test methods 26
10.6 Test conditions 27
10.7 Presentation of results 27
10.7.1 Presentation of single test results 27
10.7.2 Presentation of results of test series 28
10.8 Values to be stored in a low-cycle fatigue database 29

Annex A (informative) Measurement uncertainty 31

Annex B (informative) Examples of graphical presentation of results 33

Bibliography 37