ISO 20903:2006-07 (E)

Surface chemical analysis - Auger electron spectroscopy and X-ray photoelectron spectroscopy - Methods used to determine peak intensities and information required when reporting results

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 1

5 Methods for peak-intensity determination -- Direct spectrum 2
5.1 General 2
5.2 Selection and subtraction of an inelastic background 3
5.3 Measurement of peak intensity 4
5.3.1 Measurement of peak height 4
5.3.2 Measurement of peak area 4
5.4 Measurement of a peak intensity with computer software 5
5.5 Measurement of peak intensities for a spectrum with overlapping peaks 5
5.6 Uncertainty in measurement of peak area 6

6 Methods for peak intensity determination -- Auger-electron differential spectrum 6
6.1 General 6
6.2 Measurement of Auger-electron differential intensity 7
6.3 Uncertainties in measurement of Auger-electron differential intensity 7

7 Reporting of methods used to measure peak intensities 8
7.1 General requirements 8
7.2 Methods used to determine peak intensities in direct spectra 8
7.2.1 Intensity measurement for a single peak, as described in 5.2 and 5.3 8
7.2.2 Intensity measurements from peak fitting, as described in 5.4 and 5.5 9
7.3 Methods used to obtain and determine peak intensities in Auger-electron differential spectra 9
7.3.1 Method used to obtain differential spectra 9
7.3.2 Method used to determine peak intensities, as described in 6.2 9

Annex A (informative) Instrumental effects on measured intensities 10

Bibliography 11