ISO/IEC 8801:2026-06 (E)

Information technology - 3D printing and scanning - Data standard operating procedure (SOP)

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms,definitionsandabbreviatedterms 1
3.1 Terms and definitions 1
3.2 Abbreviated terms 2

4 3Dscannedandlabelleddatastandardoperatingprocedure(SOP) 2
4.1 General requirements 2
4.1.1 Entity 2
4.1.2 Test data quality assurance procedures 3
4.2 Documentation requirements 4
4.2.1 General 4
4.2.2 Data quality manual 4
4.3 Data level 4
4.4 Data process flow for test data SOP 4

5 Defineanddesignstage 6
5.1 General 6
5.2 Test data policy 6
5.3 Test data planning 6

6 Acquire and pre-process stage 7
6.1 General 7
6.2 Test data acquisition 7
6.2.1 Sample size 7
6.2.2 Data source 7
6.2.3 Data curation 7
6.2.4 Data augmentation 7
6.3 Test data de-identification 8
6.4 Test data transfer 8
6.5 Test data preprocessing 8
6.5.1 General 8
6.5.2 Intensity normalization 8
6.5.3 Resampling and interslice interpolation 9
6.6 Test data labelling/annotation 9
6.6.1 Reference standard 9
6.6.2 Intra-observer variability 10
6.6.3 Inter-observer variability 10

7 Validate and analyse stage 10
7.1 General 10
7.2 Test data quality control 10
7.3 Test data requirements 10
7.3.1 Test data acquisition requirements 10
7.3.2 Test data labelling requirements 11
8 Optimize and update stage 11
8.1 General 11
8.2 Test data formatting and structuring 11
8.2.1 Test original data formatting 11
8.2.2 Test labelling and annotation data formatting 11
8.3 Test data reporting 11
8.4 Test data improvement 11

Bibliography 12