ISO 7503-2:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 2: Test method using wipe-test samples

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions,symbolsandabbreviations 2
3.1 Terms and definitions 2
3.2 Symbols and abbreviated terms 3

4 Sources of surface contamination 3

5 Objectivesofthesurfacecontaminationevaluation 4

6 Strategy 4

7 Methods for evaluating surface contamination 4

8 Wipe test material 5

9 Instrumentation 5
9.1 General 5
9.2 Liquid scintillation counters 6

10 Calibration 6
10.1 Calibration of installed instruments 6
10.2 Calibration of portable instruments 6

11 Guidelines on wipe test sampling 6
11.1 General 6
11.2 Guidelines on sampling removable tritium contamination 7

12 Measurement procedure 7

13 Evaluation of measurement data 8
13.1 Calculation of the activity per unit area for measurement results of installed instruments8 13.2 Calculation of the activity per unit area for measurement results of portable instruments9 13.3 Application of ISO 11929 9

14 Wipe test uncertainties 9

15 Test report 9

Bibliography 11