ISO 7503-1:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 1: General principles

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions,symbolsandabbreviations 2
3.1 Terms and definitions 2
3.2 Symbols and abbreviated terms 3

4 Objectivesofsurfacecontaminationmeasurements 4
4.1 General 4
4.2 National and international regulations 4
4.3 Definition of the measuring programme 4

5 Direct and indirect methods of assessing surface contamination 5
5.1 General 5
5.2 Direct method 6
5.3 Indirect method (wipe tests) 6
5.4 Wipe test uncertainties 6

6 Radionuclideidentificationandspectralanalysis 6

7 Monitoring instruments 7
7.1 Selection of monitors 7
7.2 Introduction to the calibration of surface contamination instruments for direct measurement 7
7.3 Tests before first use (TBFU) 8
7.4 Periodic calibration 9
7.5 Function check 9

8 Estimationofsurfacecontaminationmonitorresponseandcalibrationfactors 9
8.1 General 9
8.2 Relationship between surface emission rate and activity 10

9 Evaluation of measurement data 12

10 Uncertainties 12
10.1 General 12
10.2 Assessment of uncertainty in the calibration factor 12
10.3 Assessment of uncertainty in the measurement 13
10.4 Wipe test uncertainties 14

11 Test report for a surface contamination instrument 14

Annex A (informative)Calibrationofsurfacecontaminationinstruments 16

Annex B (informative) Example of surface contamination estimation 21

Annex C (informative)Calibrationofdoseratemeasuringinstruments 23

Bibliography 25