DIN EN 15915:2010-12 (E)

Copper and copper alloys - Determination of silver content - Flame atomic absorption spectrometric method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 6

6 Sampling 6

7 Procedure 6
7.1 Preparation of the test portion solution -- Method A 6
7.1.1 General 6
7.1.2 Test portion 6
7.1.3 Test portion solution 6
7.2 Blank test 6
7.3 Check test 6
7.4 Establishment of the calibration curve 7
7.4.1 Preparation of the calibration solutions 7
7.4.2 Adjustment of the atomic absorption spectrometer 8
7.4.3 Spectrometric measurement of the calibration solutions 8
7.4.4 Calibration curve 8
7.5 Determination 8
7.5.1 General 8
7.5.2 Preliminary spectrometric measurement 8
7.5.3 Spectrometric measurements 9
7.6 Preparation of the test portion solution -- Method B 9
7.6.1 General 9
7.6.2 Test portion 9
7.6.3 Test portion solution 9
7.7 Blank test 9
7.8 Check test 10
7.9 Establishment of the calibration curve 10
7.9.1 Preparation of the calibration solutions 10
7.9.2 Adjustment of the atomic absorption spectrometer 11
7.9.3 Spectrometric measurement of the calibration solutions 12
7.9.4 Calibration curve 12
7.10 Determination 12
7.10.1 General 12
7.10.2 Preliminary spectrometric measurement 12
7.10.3 Spectrometric measurement 12

8 Expression of results 12
8.1 Use of the calibration curve 12
8.2 Use of bracketing method 13

9 Precision 13

10 Test report 15

Bibliography 16