DIN EN 15063-1:2015-03 (E)

Copper and copper alloys - Determination of main constituents and impuritie s by wavelength dispersive X-ray fluorescence spectrometry (XRF) - Part 1: Guidelines to the routine method

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Principle 5

3 Terms and definitions 5

4 Instrumentation 7
4.1 Principles of X-ray fluorescence spectrometers 7
4.2 X-ray tubes 8
4.3 Vacuum system 9
4.4 Test sample spinner 9
4.5 Filters 9
4.6 Collimators of slits 10
4.7 Analysing crystals 10
4.8 Counters 11
4.9 Simultaneous and sequential Instruments 12

5 Sampling and test sample preparation 12

6 Evaluation methods 12
6.1 General 12
6.2 Dead time correction 12
6.3 Background correction 13
6.4 Line interference correction models 13
6.5 Inter-element effects correction models 13

7 Calibration procedure 14
7.1 General 14
7.2 Optimizing of the diffraction angle (2) 15
7.3 Selecting optimum conditions for detectors 15
7.4 Selecting optimum tube voltage and current 15
7.5 Selecting minimum measuring times 15
7.6 Selecting calibration samples 15
7.7 Selecting drift control and recalibration samples 16
7.8 Measuring the calibration samples 16
7.9 Regression calculations 16

8 Method validation (accuracy and precision) 16

9 Performance criteria 17
9.1 General 17
9.2 Precision test 17
9.3 Performance monitoring 17
9.4 Maintenance 17

10 Radiation protection 18

Annex A (informative) Example of calculating background equivalent concentration, limit of detection, limit of quantification and lower limit of detection 19

Annex B (informative) Example of calculating line interference of one element to another 21

Annex C (informative) Example of performance criteria obtained under repeatability conditions 22

Bibliography 23