ISO 2808:2019 (E)

Paints and varnishes — Determination of film thickness

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Determination of wet-film thickness

4.1 General
4.2 Mechanical methods
4.2.1 Principle
4.2.2 Field of application
4.2.3 General
4.2.4 Method 1A — Comb gauge
4.2.4.1 Description of instrument
4.2.4.2 Procedure
4.2.5 Method 1B — Wheel gauge
4.2.5.1 Description of instrument
4.2.5.2 Procedure
4.2.6 Method 1C — Dial gauge
4.2.6.1 Instrument and reference materials (reference standard)
4.2.6.1.1 Dial gauge [see Figure 3 a) and b)]
4.2.6.1.2 Reference material for zeroing the gauge
4.2.6.2 Procedure
4.3 Gravimetric method
4.3.1 Principle
4.3.2 Field of application
4.3.3 General
4.3.4 Method 2 — By difference in mass
4.3.4.1 Apparatus
4.3.4.2 Procedure
4.4 Photothermal method
4.4.1 Principle
4.4.2 Field of application
4.4.3 General
4.4.4 Method 3 — Determination using thermal properties
4.4.4.1 Instrument and reference materials (reference specimens)
4.4.4.1.1 Measurement system
4.4.4.1.2 Reference material
4.4.4.2 Calibration
4.4.4.3 Procedure

5 Determination of dry-film thickness

5.1 General
5.2 Mechanical methods
5.2.1 Principle
5.2.2 Field of application
5.2.3 General
5.2.4 Method 4A — By difference in thickness
5.2.4.1 Description of instrument
5.2.4.1.1 Micrometre
5.2.4.1.1.1 General

5.2.4.1.1.2 Version 1 — Fixed to a stand
5.2.4.1.1.3 Version 2 — Hand-held (see Figure 5)
5.2.4.1.2 Dial gauge
5.2.4.1.2.1 General
5.2.4.1.2.2 Version 1 — Fixed to a stand
5.2.4.1.2.3 Version 2 — Hand-held
5.2.4.2 Procedure
5.2.5 Method 4B — Depth gauging
5.2.5.1 Instruments and reference materials (reference specimens)
5.2.5.1.1 Version 1 — Micrometer depth gauge (see Figure 8)
5.2.5.1.2 Version 2 — Dial depth gauge (see Figure 9)
5.2.5.1.3 Reference materials for zeroing the gauge
5.2.5.2 Procedure
5.2.6 Method 4C — Surface profile scanning
5.2.6.1 Description of instrument
5.2.6.2 Procedure
5.3 Gravimetric method
5.3.1 Principle
5.3.2 Field of application
5.3.3 General
5.3.4 Method 5 — By difference in mass
5.3.4.1 Apparatus
5.3.4.2 Procedure
5.4 Optical methods
5.4.1 Principle
5.4.2 Field of application
5.4.3 General
5.4.4 Method 6A — Cross-sectioning
5.4.4.1 Version 1 — By grinding
5.4.4.1.1 Apparatus and materials
5.4.4.1.1.1 Grinding and polishing machine
5.4.4.1.1.2 Embedding medium
5.4.4.1.1.3 Grinding and polishing media
5.4.4.1.1.4 Measuring microscope
5.4.4.1.2 Procedure
5.4.4.2 Version 2 — By cutting
5.4.4.2.1 Apparatus
5.4.4.2.1.1 Cutter
5.4.4.2.1.2 Measuring microscope
5.4.4.2.2 Procedure
5.4.5 Method 6B — Wedge cut
5.4.5.1 Apparatus
5.4.5.1.1 General
5.4.5.1.2 Cutter
5.4.5.1.3 Measuring microscope or digital measurement equipment
5.4.5.2 Procedure
5.4.6 Method 6C — White-light interferometry
5.4.6.1 Instrument and reference material
5.4.6.1.1 White-light interferometer
5.4.6.1.2 Reference material
5.4.6.2 Procedure
5.5 Magnetic methods
5.5.1 Principle
5.5.2 Field of application
5.5.3 General
5.5.4 Method 7A — Magnetic pull-off gauge
5.5.4.1 Description of instrument
5.5.4.2 Procedure
5.5.5 Method 7B.1 — Magnetic-flux gauge
5.5.5.1 Description of instrument
5.5.5.2 Procedure
5.5.6 Method 7B.2 — Magnetic field change, magnetic-induction principle
5.5.6.1 Description of instrument
5.5.6.2 Procedure

5.5.7 Method 7C — Eddy-current gauge
5.5.7.1 Description of instrument
5.5.7.2 Procedure
5.6 Radiological method
5.6.1 Principle
5.6.2 Field of application
5.6.3 General
5.6.4 Method 8 — Beta backscatter method
5.6.4.1 Description of instrument
5.6.4.2 Verification
5.6.4.3 Procedure
5.7 Photothermal method
5.7.1 Principle
5.7.2 Field of application
5.7.3 General
5.7.4 Method 9 — Determination using thermal properties
5.7.4.1 Instruments and reference materials (reference specimens)
5.7.4.1.1 Measurement system
5.7.4.1.2 Reference materials
5.7.4.2 Verification
5.7.4.3 Procedure
5.8 Acoustic method
5.8.1 Principle
5.8.2 Field of application
5.8.3 General
5.8.4 Method 10 — Ultrasonic reflection
5.8.4.1 Description of instrument
5.8.4.2 Procedure
5.9 Electromagnetic method
5.9.1 Method 11 — Terahertz method
5.9.1.1 Description of instrument
5.9.1.2 Field of application
5.9.1.3 General

6 Determination of thickness of uncured powder layers

6.1 General
6.2 Gravimetric method
6.2.1 Principle
6.2.2 Field of application
6.2.3 General
6.2.4 Method 12 — By difference in mass
6.2.4.1 Apparatus
6.2.4.2 Procedure
6.3 Magnetic methods
6.3.1 Principle
6.3.2 Field of application
6.3.3 General
6.3.4 Method 13A — Magnetic-induction method
6.3.4.1 Description of instrument
6.3.4.2 Procedure
6.3.5 Method 13B — Eddy-current
6.3.5.1 Description of instrument
6.3.5.2 Procedure
6.4 Photothermal method
6.4.1 Principle
6.4.2 Field of application
6.4.3 General
6.4.4 Method 14 — Determination using thermal properties
6.4.4.1 Instruments and reference materials (reference specimens)
6.4.4.1.1 Measurement system
6.4.4.1.2 Reference materials
6.4.4.2 Verification
6.4.4.3 Procedure

7 Test report

Annex A (informative) Overview of methods

Annex B (informative) Measurement of film thickness on rough surfaces

B.1 General
B.2 Apparatus and materials
B.3 Procedure
B.3.1 Verification
B.3.2 Measurement
B.3.3 Number of readings

Annex C (informative) Factors affecting the precision of readings obtained when measuring on wooden substrates

C.1 General
C.2 Random sampling
C.3 Penetrating coating material
C.4 Orientation of measurements

Page count: 49