DIN EN ISO 2808:2007-05 (E)

Paints and varnishes - Determination of film thickness (ISO 2808:2007)

Contents

Page

Foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Determination of wet-film thickness 8
4.1 General 8
4.2 Mechanical methods 8
4.2.1 Principle 8
4.2.2 Field of application 8
4.2.3 General 8
4.2.4 Method 1A -- Comb gauge 9
4.2.5 Method 1B -- Wheel gauge 10
4.2.6 Method 1C -- Dial gauge 11
4.3 Gravimetric method 12
4.3.1 Principle 12
4.3.2 Field of application 12
4.3.3 General 12
4.3.4 Method 2 -- By difference in mass 12
4.4 Photothermal method 13
4.4.1 Principle 13
4.4.2 Field of application 13
4.4.3 General 14
4.4.4 Method 3 -- Determination using thermal properties 14

5 Determination of dry-film thickness 14
5.1 General 14
5.2 Mechanical methods 14
5.2.1 Principle 14
5.2.2 Field of application 15
5.2.3 General 15
5.2.4 Method 4A -- By difference in thickness 16
5.2.5 Method 4B -- Depth gauging 18
5.2.6 Method 4C -- Surface profile scanning 20
5.3 Gravimetric method 21
5.3.1 Principle 21
5.3.2 Field of application 21
5.3.3 General 21
5.3.4 Method 5 -- By difference in mass 21
5.4 Optical methods 22
5.4.1 Principle 22
5.4.2 Field of application 23
5.4.3 General 23
5.4.4 Method 6A -- Cross-sectioning 24
5.4.5 Method 6B -- Wedge cut 25
5.5 Magnetic methods 25
5.5.1 General 25

5.5.2 Principle 25
5.5.3 Field of application 25
5.5.4 General 26
5.5.5 Method 7A -- Magnetic pull-off gauge 26
5.5.6 Method 7B -- Magnetic-flux gauge 27
5.5.7 Method 7C -- Magnetic-induction gauge 27
5.5.8 Method 7D -- Eddy-current gauge 28
5.6 Radiological method 29
5.6.1 Principle 29
5.6.2 Field of application 29
5.6.3 General 29
5.6.4 Method 8 -- Beta backscatter method 30
5.7 Photothermal method 30
5.7.1 Principle 30
5.7.2 Field of application 31
5.7.3 General 31
5.7.4 Method 9 -- Determination using thermal properties 32
5.8 Acoustic method 32
5.8.1 Principle 32
5.8.2 Field of application 32
5.8.3 General 32
5.8.4 Method 10 -- Ultrasonic thickness gauge 33

6 Determination of thickness of uncured powder layers 33
6.1 General 33
6.2 Gravimetric method 34
6.2.1 Principle 34
6.2.2 Field of application 34
6.2.3 General 34
6.2.4 Method 11 -- By difference in mass 34
6.3 Magnetic methods 34
6.3.1 Principle 34
6.3.2 Field of application 34
6.3.3 General 35
6.3.4 Method 12A -- Magnetic-induction gauge 35
6.3.5 Method 12B -- Eddy-current gauge 36
6.4 Photothermal method 36
6.4.1 Principle 36
6.4.2 Field of application 36
6.4.3 General 36
6.4.4 Method 13 -- Determination using thermal properties 36

7 Measurement of film thickness on rough surfaces 37
7.1 General 37
7.2 Apparatus and materials 38
7.3 Procedure 38
7.3.1 Verification 38
7.3.2 Measurement 38
7.3.3 Number of readings 38

8 Test report 38

Annex A (informative) Overview of methods 40

Bibliography 43