ISO 19085-6:2024-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie)

Contents

Page

Foreword vi

Introduction vii

1 Scope 1

2 Normative references 2

3 Terms and definitions 2

4 Safety requirements and measures for controls 9
4.1 Safety and reliability of control systems 9
4.2 Control devices 9
4.3 Start 10
4.3.1 Direct start 10
4.3.2 Start via control power-on 10
4.4 Safe stops 11
4.4.1 General 11
4.4.2 Normal stop 11
4.4.3 Operational stop 11
4.4.4 Emergency stop 11
4.5 Braking function of tools 11
4.6 Mode selection 11
4.7 Tool speed changing 11
4.7.1 Speed changing by shifting the belts on the pulleys 11
4.7.2 Speed changing by incremental speed change motor 11
4.7.3 Infinitely variable speed by frequency inverter 11
4.7.4 Speed limiting device for tenoning 11
4.7.5 Changing the direction of tool rotation 12
4.8 Failure of any power supply 12
4.9 Manual reset control 13
4.10 Standstill detection and monitoring 13
4.11 Machine moving parts speed monitoring 13
4.12 Time delay 13
4.13 Teleservice 13
4.14 Power-driven adjustment of arbor, demountable power feed unit, fences and table insert 13

5 Safety requirements and measures for protection against mechanical hazards 14
5.1 Stability 14
5.2 Risk of break-up during operation 14
5.3 Tool and tool fixing design 14
5.3.1 General 14
5.3.2 Spindle locking 17
5.3.3 Circular saw blade fixing device 17
5.3.4 Flange dimension for circular saw blades 17
5.3.5 Arbor rings 17
5.3.6 Quick tool/arbor change system 17
5.3.7 Manual adjustment of arbor height 18
5.3.8 Manual adjustment of arbor inclination 18
5.4 Braking 19
5.4.1 Braking of tools 19
5.4.2 Maximum run-down time 19
5.4.3 Brake release 19
5.5 Safeguards 19

5.5.1 Fixed guards 19
5.5.2 Interlocking movable guards 19
5.5.3 Hold-to-run control 19
5.5.4 Two-hand control 19
5.5.5 Electro-sensitive protective equipment (ESPE) 19
5.5.6 Pressure-sensitive protective equipment (PSPE) 19
5.5.7 Enabling control 20
5.6 Prevention of access to hazardous moving parts 20
5.6.1 Access to the tool below the table 20
5.6.2 Safeguarding for straight work 20
5.6.3 Safeguarding for curved work 22
5.6.4 Safeguarding for tenoning 23
5.6.5 Safeguarding the glass bead saw blade 24
5.6.6 Guarding of drives 24
5.7 Impact hazard 24
5.8 Clamping devices 24
5.9 Measures against ejection 24
5.9.1 General 24
5.9.2 Guards materials and characteristics 24
5.9.3 Anti-kickback devices 25
5.10 Workpiece supports and guides 27
5.10.1 Machine table 27
5.10.2 Workpiece guiding for straight work 30
5.10.3 Workpiece guiding for curved work 31
5.11 Safety appliances 32

6 Safety requirements and measures for protection against other hazards 32
6.1 Fire 32
6.2 Noise 32
6.2.1 Noise reduction at the design stage 32
6.2.2 Noise emission measurement and declaration 33
6.3 Emission of chips and dust 33
6.4 Electricity 33
6.5 Ergonomics and handling 33
6.6 Lighting 33
6.7 Pneumatics 33
6.8 Hydraulics 34
6.9 Electromagnetic compatibility 34
6.10 Laser 34
6.11 Static electricity 34
6.12 Errors of fitting 34
6.13 Isolation 34
6.14 Maintenance 34
6.15 Relevant but not significant hazards 34

7 Information for use 34
7.1 Warning devices 34
7.2 Marking 34
7.2.1 General 34
7.2.2 Additional markings 34
7.3 Instruction handbook 35
7.3.1 General 35
7.3.2 Additional information 35

Annex A (informative) **List of significant hazards 38**

Annex B (informative) **Performance level required 40**

Annex C (normative) **Stability test 41**

Annex D (normative) **Test for braking function 42**

Annex E (normative) **Impact test for guards 43**

Annex F (normative) **Noise test code 44**

Annex G (informative) **Determination of maximum spindle speeds for single piece arbors 47**

Annex H (normative) **Rigidity test for pressure pads, hand protectors and guiding steadies 51**

Bibliography 57