ISO 14347:2008-12 (E)

Fatigue - Design procedure for welded hollow-section joints - Recommendations

Contents

Page

Foreword iv

1 Scope 1
1.1 General 1
1.2 Materials 1
1.3 Types of joints 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols and abbreviated terms 7

5 Cumulative fatigue damage 12

6 Partial safety factor 12

7 Fatigue design procedures 12
7.1 Hot-spot stress method 12
7.2 Design procedures 13

8 Fatigue strength 13
8.1 Member forces 13
8.2 Nominal stress ranges 14
8.3 SCF calculations 14
8.4 Hot-spot stress ranges 14
8.5 Fatigue strength curves 15

9 SCF calculations for CHS joints 17
9.1 Uniplanar CHS T- and Y-joints 17
9.2 Uniplanar CHS X-joints 18
9.3 Uniplanar CHS K-joints with gap 18
9.4 Multiplanar CHS XX-joints 19
9.5 Multiplanar CHS KK-joints with gap 20
9.6 Minimum SCF values 21

10 SCF calculations for RHS joints 21
10.1 Uniplanar RHS T- and X-joints 21
10.2 Uniplanar RHS K-joints with gap 22
10.3 Uniplanar RHS K-joints with overlap 23
10.4 Multiplanar RHS KK-joints with gap 24
10.5 Minimum SCF values 25

Annex A (normative) Quality requirements for hollow sections 26

Annex B (normative) Weld details 27

Annex C (informative) A fatigue assessment procedure 29

Annex D (normative) SCF equations and graphs for CHS joints 31

Annex E (normative) SCF equations and graphs for RHS joints 47

Bibliography 67