ISO 15472:2010-05 (E)

Surface chemical analysis — X-ray photoelectron spectrometers — Calibration of energy scales

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Symbols and abbreviated terms 1

4 Outline of method 2

5 Procedure for calibrating the energy scale 5
5.1 Obtaining the reference samples 5
5.2 Mounting the samples 6
5.3 Cleaning the samples 6
5.4 Choosing the spectrometer settings for which energy calibration is required 6
5.5 Operating the instrument 6
5.6 Options for initial or subsequent calibration measurements 7
5.7 Measurements for the peak binding-energy repeatability standard deviation and the scale linearity 7
5.8 Calculating the peak binding-energy repeatability standard deviation 8
5.9 Checking the binding-energy scale linearity 11
5.10 Procedure for the regular determination of the calibration error 12
5.11 Procedures for correction of the instrument binding-energy scale 13
5.12 Next calibration 15
5.13 Establishing the calibration interval 15

Annex A (normative) **Least-squares determination of the peak binding energy by a simple computational method** 16

Annex B (informative) **Derivation of uncertainties** 19

Annex C (informative) **Citation of the uncertainties of measured binding energies** 21

Annex D (informative) **Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source** 23

Bibliography 26