DIN ISO 15472:2020-05 (E)

Surface chemical analysis - X-ray photoelectron spectrometers - Calibration of energy scales (ISO 15472:2010); Text in English

Contents

Page

Foreword ..... **iv**

Introduction ..... **v**

1 Scope **1**

2 Normative references **1**

3 Symbols and abbreviated terms **1**

4 Outline of method **2**

5 Procedure for calibrating the energy scale **5**
5.1 Obtaining the reference samples **5**
5.2 Mounting the samples **6**
5.3 Cleaning the samples **6**
5.4 Choosing the spectrometer settings for which energy calibration is required **6**
5.5 Operating the instrument **6**
5.6 Options for initial or subsequent calibration measurements **7**
5.7 Measurements for the peak binding-energy repeatability standard deviation and the scale linearity **7**
5.8 Calculating the peak binding-energy repeatability standard deviation **8**
5.9 Checking the binding-energy scale linearity **11**
5.10 Procedure for the regular determination of the calibration error **12**
5.11 Procedures for correction of the instrument binding-energy scale **13**
5.12 Next calibration **15**
5.13 Establishing the calibration interval **15**

Annex A (normative) **Least-squares determination of the peak binding energy by a simple computational method** **16**

Annex B (informative) **Derivation of uncertainties** **19**

Annex C (informative) **Citation of the uncertainties of measured binding energies** **21**

Annex D (informative) **Measurements of modified Auger parameters measured using XPS instruments equipped with a monochromated Al X-ray source** **23**

Bibliography **26**