ISO 3951-1:2013-09 (E)

Sampling procedures for inspection by variables - Part 1: Specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection for a single quality characteristic and a single AQL

Contents

Page

Foreword vi

Introduction viii

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols 5

5 Acceptance quality limit (AQL) 6
5.1 Concept 6
5.2 Use 6
5.3 Specifying AQLs 6
5.4 Preferred AQLs 7
5.5 Caution 7
5.6 Limitation 7

6 Switching rules for normal, tightened, and reduced inspection 7

7 Relation to ISO 2859-1 7
7.1 Similarities 7
7.2 Differences 8

8 Consumer protection 9
8.1 Use of individual plans 9
8.2 Consumer's risk quality (CRQ) tables 9
8.3 Producer's risk tables 9
8.4 Operating characteristic (OC) curves 9

9 Allowing for measurement uncertainty 9

10 Planning 10

11 Choice between variables and attributes 10

12 Choice between the s-method and -method 11

13 Choice of inspection level and AQL 11

14 Choice of sampling scheme 11
14.1 Standard plans 11
14.2 Special plans 12

15 Preliminary operations 12

16 Standard procedures for the s-method 12

16.1 Obtaining a plan, sampling, and preliminary calculations 12
16.2 Acceptability criteria for single specification limits 13
16.3 Graphical method for a single specification limit 14
16.4 Acceptability criterion for combined control of double specification limits 15
16.4.1 General 15
16.4.2 Procedure for sample size 3 15
16.4.3 Procedure for sample size 4 17
16.4.4 Procedure for sample sizes greater than 4 18

17 Standard procedures for the -method 20
17.1 Obtaining a plan, sampling, and preliminary calculations 20
17.2 Acceptability criteria for a single specification limit 20
17.3 Acceptability criterion for combined control of double specification limits 21

18 Procedure during continuing inspection 22

19 Normality and outliers 23
19.1 Normality 23
19.2 Outliers 23

20 Records 23
20.1 Control charts 23
20.2 Lots that are not accepted 23

21 Operation of switching rules 23

22 Discontinuation and resumption of inspection 24

23 Switching between the s-method and -method 24
23.1 Estimating the process standard deviation 24
23.2 State of statistical control 25
23.3 Switching from the s-method to the -method 25
23.4 Switching from the -method to the s-method 25

24 Charts B to R -- Operating characteristic curves and tabulated values for single sampling plans, normal inspection: s-method 27
24.1 Operating characteristic curves and tabulated values for sample size code letter B: s-method 27
24.2 Operating characteristic curves and tabulated values for sample size code letter C: s-method 28
24.3 Operating characteristic curves and tabulated values for sample size code letter D: s-method 29
24.4 Operating characteristic curves and tabulated values for sample size code letter E: s-method 30
24.5 Operating characteristic curves and tabulated values for sample size code letter F: s-method 31
24.6 Operating characteristic curves and tabulated values for sample size code letter G: s-method 32
24.7 Operating characteristic curves and tabulated values for sample size code letter H: s-method 33
24.8 Operating characteristic curves and tabulated values for sample size code letter J: s-method 34
24.9 Operating characteristic curves and tabulated values for sample size code letter K: s-method 35
24.10 Operating characteristic curves and tabulated values for sample size code letter L: s-method 36
24.11 Operating characteristic curves and tabulated values for sample size code letter M: s-method 37
24.12 Operating characteristic curves and tabulated values for sample size code letter N: s-method 38

24.13 Operating characteristic curves and tabulated values for sample size code letter P: s-method 39
24.14 Operating characteristic curves and tabulated values for sample size code letter Q: s-method 40
24.15 Operating characteristic curves and tabulated values for sample size code letter R: s-method 41

25 Charts s-D to s-R -- Acceptance curves for combined control of double specification limits: s-method 42

Annex A (normative) Table for determining the sample size code letter 55

Annex B (normative) Form k for single sampling plans: s-method 56

Annex C (normative) Form k for single sampling plans: -method 59

Annex D (normative) Values of fs for maximum sample standard deviation (MSSD) 62

Annex E (normative) Values of f for maximum process standard deviation (MPSD) 65

Annex F (normative) Estimating the process fraction nonconforming for sample size 3: s-method 66

Annex G (normative) Single sampling plans of Form p* 69

Annex H (normative) Values of cU for upper control limit on the sample standard deviation 70

Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection 71

Annex J (normative) Procedures for obtaining s and 72

Annex K (informative) Consumer's risk qualities 74

Annex L (informative) Producer's risks 78

Annex M (informative) Operating characteristics for the -method 82

Annex N (informative) Estimating the process fraction nonconforming for sample sizes 3 and 4: s-method 83

Annex O (normative) Accommodating measurement variability 86

Bibliography 91