ISO 8769:2020 (E)

Measurement of radioactivity — Alpha-, beta- and photon emitting radionuclides — Reference measurement standard specifications for the calibration of surface contamination monitors

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Traceability of reference measurement standards

5 Specification of reference measurement standards

- 5.1 General
- 5.2 Class 1 reference measurement standards
- 5.2.1 General requirements
- 5.2.2 Activity and surface emission rate
- 5.2.3 Uniformity
- 5.2.4 Radionuclides
- 5.3 Class 2 reference measurement standards
- 5.3.1 General requirements
- 5.3.2 Activity and surface emission rate
- 5.3.3 Uniformity
- 5.3.4 Radionuclides
- 5.4 Working measurement standard
- 5.4.1 General requirements
- 5.4.2 Activity and surface emission rate
- 5.4.3 Uniformity
- 5.4.4 Radionuclides

6 Transfer measurement devices

- 6.1 Transfer measurement device for alpha-radiation and beta-radiation
- 6.2 Transfer measurement device for photon-radiation
- 6.3 Calibration

Annex A (informative) Particular considerations for reference measurement standards emitting electrons of energy less than 0,15 MeV and photons of energy less than 1,5 MeV

Page count: 13