ISO 9978:2020 (E)

Radiation protection — Sealed sources — Leakage test methods

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Requirements

5 Test methods by radioactive means

- 5.1 Immersion tests
- 5.1.1 Immersion test (hot liquid)
- 5.1.2 Immersion test (boiling liquid)
- 5.1.3 Immersion test with a liquid scintillator
- 5.1.4 Immersion test at room temperature
- 5.1.5 Acceptance criteria
- 5.2 Gaseous emanation tests
- 5.2.1 Gaseous emanation test by absorption (for radium-226 sealed sources)
- 5.2.2 Gaseous emanation test by immersion with a liquid scintillator (for radium-226 sealed sources)
- 5.2.3 Gaseous emanation test (for krypton-85 sealed sources)
- 5.2.4 Other gaseous emanation tests
- 5.2.5 Acceptance criteria
- 5.3 Wipe tests
- 5.3.1 Wet wipe test
- 5.3.2 Dry wipe test
- 5.3.3 Acceptance criteria

6 Test methods by volumetric means

- 6.1 Helium mass spectrometer leakage tests
- 6.1.1 Helium test [equivalent to leak test type B6 in ISO 20485]
- 6.1.2 Helium pressurisation test [equivalent to leak test type B5 in ISO 20485]
- 6.1.3 Acceptance criteria
- 6.2 Bubble leakage tests
- 6.2.1 Vacuum bubble test [equivalent to immersion technique using vacuum in EN 1593[6]
- 6.2.2 Hot-liquid bubble test [equivalent to immersion technique using liquid at elevated temperature in EN 1593[6]
- 6.2.3 Gas pressurisation bubble test [equivalent to immersion technique using pressurisation of the object in EN 1593[6]
- 6.2.4 Liquid nitrogen bubble test
- 6.2.5 Acceptance criteria
- 6.3 Water pressurisation test

Annex A (informative) Guidance for the choice of the tests to be carried out according to purpose and sealed source type

- A.1 General
- A.2 Leakage test for the production of sealed sources
- A.3 Leakage tests for test sources used for classification testing to ISO 2919
- A.4 Periodic inspections

Page count: 13