# ISO 6980-3:2023-11 (E)

## Nuclear energy - Reference beta-particle radiation - Part 3: Calibration of area and personal dosemeters and the determination of their response as a function of beta radiation energy and angle of incidence

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Normative references ..... 1

3 Termsanddefinitions ..... 1

4 Symbols and abbreviated terms, and reference and standard test conditions ..... 3

5 Procedures applicable to all area and personal dosemeters ..... 4
5.1 General principles ..... 4
5.1.1 Selection of sources and radiation qualities ..... 4
5.1.2 Reference absorbed dose rate ..... 4
5.1.3 Conversion coefficients ..... 5
5.1.4 Reference conditions and standard test conditions ..... 5
5.1.5 Variation of influence quantities ..... 5
5.1.6 Point of test and reference point ..... 6
5.1.7 Axes of rotation ..... 6
5.1.8 Condition of the dosemeter to be calibrated ..... 6
5.1.9 Influence of photon contribution ..... 6
5.2 Determination of calibration and correction factors ..... 6
5.2.1 Determination of the reference dose rate by a standard instrument ..... 6
5.2.2 Determination of reference calibration factor and correction factor for non-linear response ..... 7
5.2.3 Determination of the correction factor for beta-particle energy and angle of incidence, kE, ..... 7

6 Procedures for area dosemeters ..... 8
6.1 General principles ..... 8
6.2 Quantity to be measured ..... 8

7 Procedures for personal dosemeters ..... 8
7.1 General principles ..... 8
7.2 Quantity to be measured ..... 8
7.3 Experimental conditions ..... 8
7.3.1 Use of phantoms ..... 8
7.3.2 Geometrical considerations in divergent beams ..... 9
7.3.3 Simultaneous irradiation of several dosemeters ..... 9

8 Uncertainties ..... 10

9 Reporting of results according to ISO 17025 ..... 10

Annex A (normative) Reference conditions and standard test conditions ..... 11

Annex B (informative)Conversioncoefficientsforsomebetareferenceradiationfields ..... 13

Bibliography ..... 19