# ISO/TR 18336:2016-02 (E)

## Guidelines for good XRF laboratory practice for the iron ore industry

## Contents

Page


Foreword ..... iv

Introduction ..... v

1 Scope ..... 1

2 Reagents ..... 1

3 Apparatus ..... 2

4 Fused glass beads ..... 5
4.1 General ..... 5
4.2 Storage ..... 5
4.3 Disc making precision ..... 5
4.4 Bead distortion (curvature and flatness) ..... 6

5 Quality control ..... 6
5.1 Selection of QC samples and frequency of preparation ..... 6
5.2 Analysis of QC and analytical samples ..... 7
5.3 Control charts ..... 7
5.4 Participation in proficiency test programs ..... 8

Annex A (informative) Results for flux loss on ignition testing ..... 9

Annex B (informative) Procedure to check disc making precision ..... 10

Annex C (informative) Method to determine relationship between height and concentration ..... 11

Annex D (informative) Production of a height adjustable cup ..... 12

Annex E (informative) Bead measurement apparatus ..... 13

Annex F (informative) Flow sheet for fused bead quality ..... 14

Annex G (informative) Microsoft Excel program for calculating disc precision ..... 15

Annex H (informative) Data input screen for calculating disc precision ..... 19

Annex I (informative) Loss of accuracy with no loss of precision ..... 20

Annex J (informative) Loss of accuracy with loss of precision ..... 22

Annex K (informative) Loss of accuracy and precision -- Loss of bead making precision ..... 23

Annex L (informative) Results for spectrometer precision test ..... 25

Annex M (informative) Drift correction ..... 26

Bibliography ..... 27