ISO5418-2 :2006-12 (E)

Iron ores_- Determination of copper_- Part_2: Flame atomic absorption spectrometric method

Contents

Page

Foreword ..... **iv**

1 Scope **1**

2 Normative references **1**

3 Principle **1**

4 Reagents **2**

5 Apparatus **3**

6 Sampling and samples **3**
6.1 Laboratory sample **3**
6.2 Preparation of predried test samples **4**

7 Procedure **4**
7.1 Number of determinations **4**
7.2 Blank test and check test **4**
7.3 Test portion **4**
7.4 Determination **4**
7.4.1 Decomposition of the test portion **4**
7.4.2 Treatment of the solution **5**
7.4.3 Preparation of the set of calibration solutions **5**
7.4.4 Adjustment of atomic absorption spectrometer **5**
7.4.5 Atomic absorption measurements **6**

8 Expression of results **6**
8.1 Calculation of mass fraction of copper **6**
8.2 General treatment of results **6**
8.2.1 Repeatability and permissible tolerance **6**
8.2.2 Determination of analytical result **7**
8.2.3 Between-laboratories precision **7**
8.2.4 Check for trueness **8**
8.2.5 Calculation of final result **8**
8.3 Oxide factor **9**

9 Test report **9**

Annex A (normative) **Flowsheet of the procedure for the acceptance of analytical values for test samples** **10**

Annex B (informative) **Derivation of repeatability and permissible tolerance equations** **11**

Annex C (informative) **Precision data obtained by international analytical trials** **12**