ISO 16042:2007-02 (E)

Iron ores - Guidelines for the use of certified reference materials (CRMs)

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 1

5 Ore types 2

6 Mass-fraction difference 2

7 Extraction of the test portion 2

8 Two-bottle strategy 3

9 Alteration of the CRM 3

10 Shewhart control charts 3

11 Acceptance of analytical values 4

12 Test report 4

Annex A (informative) Example of the calculation of mass-fraction difference 5