ISO 9370:2009-07 (E)

Plastics - Instrumental determination of radiant exposure in weathering tests - General guidance and basic test method

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Significance and use 6
4.1 General considerations 6
4.2 Natural weathering -- Fixed-angle or equatorial-mount exposure 6
4.3 Accelerated natural weathering -- Solar-concentrating exposures using Fresnel-reflecting concentrators 7
4.4 Artificial accelerated weathering and artificial accelerated irradiation 7

5 Apparatus 8
5.1 General 8
5.2 Non-selective radiometers (see Table 1) 9
5.3 Selective (UV) radiometers (see Table 2) 10
5.4 Recorders and data loggers 10

6 Calibration 10
6.1 General 10
6.2 Reference and field radiometers 11
6.3 Selective reference radiometers 11
6.4 Selective field radiometers 12
6.5 Other requirements 12

7 Procedure 12
7.1 Natural weathering -- Fixed-angle or equatorial-mount exposure 12
7.2 Accelerated natural weathering -- Solar concentrating exposures using Fresnel-reflecting concentrators 12
7.3 Artificial accelerated weathering or artificial accelerated irradiation 13

8 Exposure report 13

Annex A (informative) Comparison of typical wide-band UV radiometers 14

Bibliography 15