ISO 1183-1:2012-05 (E)

Plastics - Methods for determining the density of non-cellular plastics - Part 1: Immersion met hod, liquid pyknometer method and titration method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Conditioning 2

5 Methods 2
5.1 Method A -- Immersion method 2
5.2 Method B -- Liquid pyknometer method 4
5.3 Method C -- Titration method 5

6 Correction for buoyancy in air 6

7 Test report 7

Annex A (informative) Liquid systems suitable for use in Method C 8

Annex B (informative) Correction for buoyancy in air 9

Bibliography 10