ISO 11357-2:2013-05 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 2: Determination of glass transition temperature and glass transition step height

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 2

5 Apparatus and materials 2

6 Test specimens 2

7 Test conditions and specimen conditioning 2

8 Calibration 2

9 Procedure 2
9.1 Setting up the apparatus 2
9.2 Loading the test specimen into the crucible 2
9.3 Insertion of crucibles 2
9.4 Temperature scan 2

10 Expression of results 3
10.1 Determination of glass transition temperatures 3
10.2 Determination of glass transition step height 5

11 Precision 5

12 Test report 5

Bibliography 6