DIN EN 16795:2016-03 (E)

Plastics - Method for estimating heat build up of flat surfaces by simulated solar radiation

Contents

Page

European foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Abbreviations 5

5 Principle 5

6 Apparatus 6
6.1 General 6
6.2 Test chamber 6
6.3 Laboratory radiation source 6
6.4 Radiometer 7
6.5 Test chamber temperature and relative humidity 7
6.6 Surface temperature measurement device 7
6.7 Black and white standard thermometer 8
6.8 Defined airflow directed across the sample 9
6.9 Specimen holders 9

7 Test specimens 9
7.1 Form, shape and preparation 9
7.2 Number of test specimens 9

8 Exposure conditions 9
8.1 Radiation 9
8.2 Black and white standard thermometer 9
8.3 Chamber air temperature 10
8.4 Relative humidity of chamber air 10
8.5 Wind speed 10
8.6 Sets of exposure conditions 10

9 Procedure 10
9.1 General 10
9.2 Mounting the test specimens 10
9.3 Exposure 10
9.4 Measurement of the surface temperature 11

10 Test report 11

Bibliography 12