ISO 1183-3:1999-09 (E)

Plastics - Methods for determining the density of non-cellular plastics - Part 3: Gas pyknometer method

Contents

Page

1 Scope 1

2 Terms, definitions, symbols, units and abbreviated terms 1

3 Principle 2

4 Apparatus and materials 3

5 Test specimens 3

6 Calibration 3

7 Procedure and calculation 4

8 Precision 4

9 Test report 4

Annex A (informative) Two-chamber pressure-measuring pyknometer 6