ISO 16014-4:2003-04 (E)

Plastics - Determination of average molecular mass and molecular mass distribution of polymers using size-exclusion chrom atography - Part 4: High-temperature method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 1

5 Reagents 1

6 Apparatus 2

7 Procedure 4

8 Data acquisition and processing 6

9 Expression of results 6

10 Precision 6

11 Test report 8

Annex A (informative) Further information on applicability of method 9

Annex B (informative) Further information on reagents 10

Bibliography 12