DIN EN 13999-1:2006-11 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solvent- free adhesives after application - Part 1: General procedure

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 6

4 Principle 6

5 Apparatus 6
5.1 Support 6
5.2 Adhesive coating device 7
5.3 Emission test chamber 7
5.4 Air supply and mixing facilities 7
5.5 Air sampling devices 8
5.6 Devices for desorption and analysis 8

6 Adhesive sample 8
6.1 General 8
6.2 Pre-conditioning 8
6.3 Preparation of a test specimen 8

7 Procedure 9
7.1 Number of determinations 9
7.2 Preconditioning of the test chamber 9
7.3 Operation of the test chamber 9
7.4 Starting of the test 9
7.5 Sampling and analysis of emitted substances 9

8 Expression of results 10
8.1 Calculations 10
8.2 Carcinogenic and sensitising compounds concentration 10
8.3 Volatile organic compounds 10
8.3.1 General 10
8.3.2 Determination of the specific emission rate at the sampling times 11
8.3.3 Determination of the specific cumulative emission in the 24 h to 240 h interval 11
8.3.4 Determination of the empirical parameters a and b 12

9 Test report 13

Annex A (normative) Carcinogenic and sensitising substances 14

Annex B (informative) Theoretical background of the calculation method 15

B.1 Determination of the specific emission rate 15
B.2 Determination of the specific cumulative emission in the 24 h to 240 h interval 15

Bibliography 18