ISO 8988:2006-09 (E)

Plastics - Phenolic resins - Determination of hexamethylenetetramine content - Kjeldahl method, perchloric acid method and hydrochlor ic acid method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Kjeldahl method 1

4 Perchloric acid method 3

5 Hydrochloric acid method 5

6 Test report 7