DIN 5035-6:1990-12 (E)

Artificial lighting; measurement and evaluation

Contents

	Page
1 Field of application	2
2 Scope	2
3 Quantities	2
4 Instrumentation	2
4.1 Limits of error	2
4.2 Luxmeter	2
4.3 Instrument for measuring cylindrical illuminance	3
4.4 Luminance meter	3
4.5 Instrument for measuring reflectance under diffuse incident light	3
4.6 Voltmeter	3
5 Preparation of measurement	3
5.1 General	3
5.2 Lighting system	3
6 Measurement procedure	3
6.1 General	3
6.2 Elimination of stray light	4
6.3 Supply voltage and ambient temperature	4
6.4 Measurement of illuminance	4
6.4.1 General	4
6.4.2 Empty rooms	4
6.4.3 Furnished rooms	4
6.4.4 Illuminance at workplaces	4
6.4.5 Illuminance in circulation areas	4
6.4.6 Uniformity of local workplace lighting	4
6.5 Measurement of cylindrical illuminance	5
6.6 Measurement of luminance	5
6.7 Determination of luminance of luminaires	5
6.8 Measurement of reflectance	5
6.9 Determination of cut-off angle	5
7 Evaluation and presentation of results	6
7.1 Correction of measured values	6
7.2 Illuminance	6
7.3 Cylindrical illuminance and reflectances	6
7.4 Luminance distribution in the interior	6
7.5 Limitation of direct glare	7
7.6 Colour appearance and colour rendering	7
8 Special provisions for the measurement and evaluation of escape lighting	7
8.1 Special parameters	7
8.2 Measurement procedure for escape lighting	7
8.2.1 General	7
8.2.2 Elimination of stray light	7
8.2.3 Measurement of response time	7
8.2.4 Measurement of illuminance	7
8.2.5 Limitation of direct glare	7
8.2.6 Minimum luminance and luminance contrast for illuminated emergency signs	7
8.2.7 Uniformity of luminance for emergency signs	8
8.2.8 Visual impact and legibility of safety signs and colours	8
9 Special provisions for the measurement and evaluation of safety lighting at high-risk workplaces	10
9.1 Special parameters	10
9.2 Measurement procedure	10
9.2.1 Response time	10
9.2.2 Illuminance	10
9.2.3 Limitation of direct glare	10
9.2.4 Visual impact and legibility of safety signs and colours	10
10 Special provisions for measurement and evaluation of operating field lighting	10
10.1 Special parameters	10
10.2 Instrumentation	10
10.2.1 Luxmeter for measuring illuminance distribution	10
10.2.2 Luxmeter for measurements using set-up shown in figure 13	10
10.2.3 Colorimeter	10
10.2.4 Irradiance meter	10
10.2.5 Device for measuring the cavity ratio, shadow ratio and cavity shadow ratio	10
10.3 Measurement procedure	10
10.3.1 Measurement of illuminance and its distribution	10
10.3.2 Measurement of colour appearance	10
10.3.3 Measurement of irradiance	10
10.3.4 Measurements to determine cavity ratio, shadow ratio and cavity shadow ratio	10
11 Test report	11